

A 351461

Certified, Filed and or Recorded on  
Nov. 04, 2008 AT 12:32PM

Signed: BW  
MARILYN J NOVAK G V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 5, Township 38, Range 29  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-29-08 found a R.R. SPK

left monument as found       lowered monument       removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_

32  
5

YARD

FIELD

175TH ST. NE

FIELD

FIELD

RIVOT IN  
CMP 2565

3897  
PK IN PP

PK IN CMP

45°

FIELD RD.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]  
Deputy County Surveyor  
License No. 43932

Date: 11/3/08

**Statement of Evidence:****B051**

North Quarter Corner of Section 5, Township 38 North, Range 29 West, Alberta Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post and bearing trees noted as:

8" Poplar                      N 57 E                      13 links

6" Poplar                      S 51 W                      4 links

Line trees were noted as a 8" W Oak East 18.50 chains and a 6" Poplar West 19.38 chains.

1914 Phil Randall , in the Morrison County Surveyor's Record Book A, page 171, notes he set a stake for the corner at the lost position, measuring 5338.0 feet between section corners. Survey was for laying out a township road along the south line of Section 32, 39-29.

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services, Inc. found a RR Spike in the centerline of 175<sup>th</sup> St. NE. Measured 2667.54 feet the NW corner and 2667.74 feet to the NE corner of section 5. RR Spike fits 1914 lost position for this corner. RR Spike is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-196669.453

E-517829.668