

Certified, Filed and or Recorded on  
Nov. 04, 2008 AT 12:29PM

Signed: BW  
MARILYN J NOVAK G V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH EAST Corner of Section 8, Township 38, Range 29  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-28-08 found a 1/2" SOLID IRON PIPE

left monument as found     lowered monument     removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]  
Deputy County Surveyor  
License No. 43932

Date: 11/2/08

Statement of Evidence:

B082

Northeast Corner of Section 8, Township 38 North, Range 29 West, Alberta Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

|        |        |          |
|--------|--------|----------|
| 9" Ash | S 80 E | 35 links |
| 8" Ash | N 81 W | 9 links  |

Undated(pre-1900) County Surveyor's Record Book 2, page 244, notes the following new BT:

|         |          |          |
|---------|----------|----------|
| 14" Elm | N 16 ½ E | 27 links |
|---------|----------|----------|

1939 County Engineer's Notebook No. 128 contains survey of CAR 22 running east to west on section line. Corner is shown as a stake in center of 4-way road intersection. Ties:

|    |    |      |
|----|----|------|
| FP | SE | 44.0 |
| FP | SW | 50.2 |

1962 County Surveyor's Record Book 2, page 246, notes a set iron over a wood stake

|    |    |       |
|----|----|-------|
| TP | SW | 50.5  |
| PP | NE | 54.85 |

1964 County Engineer's Notebook No. 276 contains a road survey for CSAH No. 22 running west to east on section line. Notes show corner marked by an iron in center of road with town road north and south. Ties are the same as in 1974.

1969 County Engineer Kotsmith notes the following reference ties:

|        |    |      |
|--------|----|------|
| Cor FP | NW | 56.8 |
| PP     | NE | 55.0 |
| TP     | SW | 50.8 |

1974 County Surveyor's Record Book 2, pages 244 & 246, notes the following reference ties to an iron over a wood stake:

|                |    |      |
|----------------|----|------|
| Stop Sign Post | NW | 51.0 |
| PP             | NE | 54.9 |
| Tele Ped       | SW | 53.8 |

2008 Westwood Professional Services, Inc. found a ½" solid iron pin at the intersection of roads north/south/east/west. Found ties fitting 1974, 1969 and 1962 ties. ½" iron pin is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-191349.151  
E-521009.273