

Certified, Filed and or Recorded on  
Sep. 23, 2008 AT 01:23PM

Signed: BW  
MARILYN J NOVAK RV  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 29, Township 36, Range 28  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 8-18-08 found a 1" IRON PIPE WITH PLASTIC CAP "RLS 16095"  
AT 1'± ABOVE GROUND

left monument as found       lowered monument       removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



BENTON Co. COORDINATES  
NAD 83 (196 ADJ.)  
N = 108,300.237  
E = 553,329.499

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jason W. Oleg  
Deputy Benton County Surveyor  
License No. 45872

Date: 8-18-08

Benton County Surveyor's Office  
 Jason W. Oberg, Deputy County Surveyor  
 Minnesota License No. 45872

**Statement of Evidence:****J293**

The East Quarter Corner of Section 29, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

6" Blk Oak	S 71 W	133 links
8" Bur Oak	S 33 E	284 links

1920 County ties to iron:

6" Br. Oak	SW	87.78
8" Br. Oak	SE	187.40

1929 County Surveyor's Record Book 1, page 65 and County Surveyor's Record Book A, Map No. 49, shows a survey of Section 28 by M.B. Lang. Corner is shown marked by an iron shaft with distances of 2640 feet to the NE and SE corners of Section 29. Ties:

8" R. Oak	S 28 E	29.6 feet
12" W. Oak	N 81 W	34.7 feet

2008 The Benton County Surveyor's Office searched and found a 1" iron pipe with cap inscribed "RLS 16095", at 1 ft. ± above the ground. The reference trees from M.B. Lang's 1929 survey were also found to be in existence and were in agreement with the pipe position. Comparing distances between the Northeast and Southeast corners of the Section gives 2641.00 ft. to the NE corner and 2641.50 ft. to the SE corner, which is in harmony with Lang's 1929 measurements. The Deputy Surveyor left the iron pipe in place and accepts said iron pipe as the best evidence.

County Coordinates  
 NAD 83 (1996 Adjustment)  
 N- 108,300.237  
 E- 553329.499