

Certified, Filed and or Recorded on
Oct. 07, 2008 AT 02:50PM


Signed: BW
MARILYN J NOVAK B V
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 22, Township 36, Range 28
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09/29/08 found a 1/2" IRON PIPE OPEN
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



15
22

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oley
Deputy Benton County Surveyor
License No. 45872

Date: 10/06/08

Benton County Surveyor's Office
Jason W. Oberg, Deputy County Surveyor
Minnesota License No. 45872

Statement of Evidence:

J221

The North Quarter of Section 22, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post with bearing trees noted as:

12" Elm N 88 ½ E 612 links

1926 County Surveyor's Record Book 1, pages 51 and 52, and Map No. 48 contains a survey of Section 22 by Harry Elletson. (Notes in Notebook 48) He states that all evidence destroyed and he found no evidence of this corner or of the bearing tree. He set the corner lost, measuring 5265.60 feet between section corners. He set an iron monument.

2008 The County Surveyor's Office searched and found a ½" open iron pipe at the centerline of an east-west gravel road and approximately 3 ft., more or less, west of the centerline of a north-south ditch. Said ½" iron pipe falls 4.97 ft. east and 4.54 ft. south from a lost position. Comparing east-west 1/16th distances from occupation lines along the north line of Section 22 did not suggest either a lost position or the found ½" iron pipe. Based upon observed occupation, the Surveyor believes that the ½" iron pipe position represents the best evidence and is within acceptable limits from a lost position as referenced in 1926.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N- 116327.526
E- 561081.776