

Certified, Filed and or Recorded on
Nov. 04, 2008 AT 12:36PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 33, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-15-08 found a BROKEN CAST IRON MONUMENT

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Benton County Surveyor's Office
 Chris Hoglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

C333

East Quarter Corner of Section 33, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

4" Aspen	S 43 E	43 links
8" Blk Oak	S 31 W	14 links

Undated County Highway notes call for a cast iron monument on the centerline of road north/south and a fence line west with the following reference ties

TP	NE	40.21
FP	W	36.65

1952 MN/DOT alignment map for TH 218 (25) shows corner assumed at center of road north-south and fence lines east-west. Gives distance of 2717.7 feet to the NE corner.

1977 Paul Wellen, LS 10461, set a 1/2" iron pipe at a fence line east/west and a centerline of a north/south road. He notes a distance of 2716.13 feet to the NE corner Sec 33 and a distance of 2699.95 feet to the SE corner Sec 33. He filed a Certificate of Location (#147254).

2002 Westwood Professional Services, Inc. found a broken off cast iron monument.

2008 Westwood Professional Services, Inc. found a broken off CIM ~1 foot east of the traveled centerline of 45th Ave. NE and on fence lines east and west. None of 1977 Wellen ties remain. Measured 2715.56 feet to NE corner and 2699.36 feet to SE corner of Section 33 which agree with 1977 Wellen measurements. CIM is accepted as marking the obliterated position for this corner.

County Coordinate Obtained by GPS

NAD 83 (1996 Adjustment)

N-167060.096

E-495048.726

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST 1/4 Corner of Section 33, Township 38, Range 30, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Filed under West 1/4 Corner Section 34, T 38 R 30

Certificate # 147254

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE DATE

Registration No. _____

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 ____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

West 1/4 _____ Corner of Section 34, Township 38, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch, ^{Set 1/2"} iron pipe at the intersection of fence lines east and west and a north-south township road.

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 6-16-77 placed a Iron Monument (1/2" Pipe)
DATE

SKETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page. #147254

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Paul E. Wellen 1/3/78
SIGNATURE DATE

Registration No. 10461

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS ^{County Recorder}
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 4 P.M. on the 10th day of January A.D., 19 78

Register of Deeds F. A. Johnson
By A. E. ^{County Recorder}, Deputy

DOCUMENT NO. _____

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

WEST 1/4 Corner of Section 34, Township 38, Range 30, 4th P.M.

STATE OF MINNESOTA, County of BENTON


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 6-16-77 placed a IRON MONUMENT (1/2" PIPE)
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature]
SIGNATURE
1/3/78
DATE

Registration No. 10461

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of BENTON
147254

I hereby certify that this document was filed in the Reg. of Deeds office at 4 P. .M. on the 02 day of January A.D., 19 78

Register of Deeds [Signature]
By [Signature] Deputy
County Recorder

DOCUMENT NO. _____

Set $\frac{1}{2}$ " iron pipe at the intersection of fence lines east and west and a north-south township road.