

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST Corner of Section 19, Township 38 N, Range 30 W, 4th P.M.

STATE OF MINNESOTA, County of BENTON

At the corner location shown on the sketch:

- On 11-23-92 found a CAST IRON MONUMENT, DOWN 0.4'
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ Placed a _____
DATE

SKETCH OF REFERENCE TIES



1983 BENTON COUNTY
COORDINATE SYSTEM
N = 180416.185
E = 483943.564

Statement of evidence relative to this corner location is on back of page.

J.B.M. JAN. 1993
WMA01555.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Bruce W. Sheppard 2-3-93
SIGNATURE DATE

Registration No. 17003

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of Benton

212984

I hereby certify that this document was filed in the Co. recorders office at 8:15 A.M. on the 8 day of February A.D., 1993

County Recorder Alice C. Longmeyer
By JW, Deputy

DOCUMENT NO. 212984

Northeast Corner Section 19, Township 38 North, Range 30 West

The DNR Bureau of Engineering contacted the following for survey information:

- Minnesota Secretary of State's Office
- MN/DOT Office in St. Paul
- MN/DOT Office in Brainerd
- Benton County Recorder's Office
- Benton County Highway Engineer's Office
- Paul E. Wellen and Associates of St. Cloud
- David Regan, RLS #12236, of St. Cloud
- Rieke Carroll Muller and Associates of St. Cloud
- William F. Lunser, RLS #9394, of St. Cloud
- Comstock and Davis Inc., of Little Falls

1852 U. S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post with the following bearing trees marked:

- 4" Black Oak, South 72 1/2° West, 53 links (34.98 feet)
- 4" Black Oak, North 29° East, 113 links (74.58 feet)

1992 November 23, DNR Bureau of Engineering found a cast iron monument at corner. Searched for but found no evidence of the record ties. The cast iron monument was found to be:

- 2764.14 feet from the east quarter corner of Section 18
- 2678.72 feet from the north quarter corner of Section 20

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found cast iron monument marks the obliterated location of the corner.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Northeast Corner of Section 19, Township 38, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 4/13/87 placed a Cast Iron Monument
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 5/5/87
SIGNATURE DATE

Registration No. 10461

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____