



# STATEMENT OF EVIDENCE

Northeast Corner of Section 36, T. 38, R. 28, Benton Co., MN.

Northwest Corner of Section 31, T. 38, R. 27, Mille Lacs Co., MN.

The line between Ranges 27 & 28, T. 38, was run by Dep. Surveyor Theo. Conkey in Oct. 1849. We were unable to find any remnants of his\* monument or accessories for this corner.

\*Please see the Certificate Of Location for the NE corner of Section 1, T. 37, R. 28, Benton County; also being the NW corner of Sec. 6, T. 37, R. 27, Mille Lacs County; for a "discussion" regarding general conditions (including GLO resurveys and "Judicial Roads") affecting the locations of the corners along this County line.

In 1994 we were hired by Benton Co. to restore certain corners along their east Co. line. Old survey notes, subsequent to the GLO notes, from both counties are as follows (in chronological order):

**Benton:** Requested from the Co. Hwy. Dept.. None provided other than GLO notes.

**Mille Lacs:** A 1911 "Plat of Road Survey" by Deputy Co. Surveyor S.L. Kennedy for a new road from the NW corner of 30-38-27 to the No. 1/4 corner of 28-38-27. Said survey shows he found the NW of 30, and restored the SW of 30, along the Co. line. (See the survey for the other corners found or restored by same) This survey shows a road on line on the W. line of 19 and the W. and So. lines of 30, but none on the W. line of 31.

A 1921 survey and plat of Sec. 30, T. 38, R. 27, by R.S. Chapman, County Surveyor. His plat states that the subject corner was a "iron pipe and rock" set at SPM along the west line of the section, and that said west line of this section was a "Judicial Road Survey". His plat gives dimensions for all the "40's" in the section as well of as angles at the corners. He also indicates that the rest of the corners along the west line of the section were all "iron pipe and rock", except for the NW corner which was a cut granite rock. No other ties are given.

There are no other subsequent surveys along the subject line that we are aware of.

On 8/19/94 we found a 2" iron pipe, down 1.5', on the centerline - centerline intersection and also fit line and distance extended W'ly from found monuments at the So. 1/4 and SE corners of Sec. 30, per Chapman's 1921 survey. The above 1911 "plat" by Kennedy indicated that Kennedy restored this corner at that time.

On 8/19/94 we left the 2" iron pipe as found and placed a 1/2" by 14" iron pipe over same and down 4".

MLCLS: /NW313827

*B. J. Englebreter*  
DEPUTY

ALICE G. ENGELBRETER  
COUNTY RECORDER

OCT 3 8 52 AM '97

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON

244643