

Certified, Filed and or Recorded on
Feb. 12, 2010 AT 12:58PM


Signed: M
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 10, Township 37, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On June 2006 found a CIM with large field stone under it.
DATE
- left monument as found lowered monument removed monument (explain)
- On 11-30-06 placed an PK NAIL
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittelsch Date 2/12/2010 License No. 19552
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:**G103**

The East Quarter Corner of Section 10, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

10" Aspen	S 68 1/2 W	56 links
10" Aspen	N 68 1/2 E	47 links

1892 County Road Book, page 71, shows road laid by out Felix Parrent on east-west ¼ line.

1932 County Engineer's notebook No. 73 contains a road survey by H. G. Elletson for SAR No. 13. Ties to a rock in 4-way road intersection:

TP	SE	34.6
FP	SW	34.6

1938 County Engineer's Notebook No. 122 contains a road survey for CAR 24 running north to south. Notes show corner marked by a large rock and hub in intersection of roads. Ties:

TP	SE	39.8
FP	SW	44.8

Stationing gives distances of 2657.9 feet to the NE corner and 2595.0 feet to the SE corner.

1954 County Surveyor's Record Book 1, page 405, (also notebook 73) notes a large rock with the following reference ties.

PP	NW	54.7
PP	NE	51.9

2006 Westwood Professional Services Inc. excavated a 10-foot x 12-foot x 4-foot deep hole to original ground. A large field stone was found down 3.5 feet under a found CIM. A PK nail was set at centerline of roads north/south/east/west in place of the found stone and CIM.

Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-156129.477
 E-500366.751