

Certified, Filed and or Recorded on  
Mar. 30, 2010 AT 11:44AM

Signed: BW  
MARILYN J NOVAK G. V. I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 16, Township 37N, Range 30W  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 11/04/08 found a CAST IRON MONUMENT DOWN 0.2'

left monument as found       lowered monument       removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock  
Benton County Surveyor  
License No. 19552

Date: 30 March 2010

**Statement of Evidence:****G163**

East Quarter Corner of Section 16, Township 37 North, Range 30 West, 4<sup>th</sup> Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

7" Bur Oak                      S 19 E                      136 links

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a CIM:

N- 150856.086

E - 495012.949

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services found a cast iron monument.

Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a CIM:

N- 150856.255

E- 495012.436

2008 The County Surveyor's Office found a cast iron monument in centerline of north-south gravel road (45<sup>th</sup> Ave NE) and a tree line (west). The Surveyor notes distances of 2650.95 ft. to the NE corner and 2670.37 ft. to the SE corner. The coordinates agree with those obtained in 1995 by Comstock and Davis and those in 2008 by Westwood Professional Services. The Surveyor accepts the cast iron monument and set ties to same.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N- 150856.332

E- 495012.410