

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 25, Township 37, Range 28, 4 P.M.

STATE OF MINNESOTA, County of BENTON

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 7/23/96 placed a 3/4" Iron Pipe (Down 0.2'±), 3' East Of Centerline
DATE

SKETCH OF REFERENCE TIES



STANDARD PROCEDURE FOR TIES:

Tree ties are to the head of a pole barn nail w/red ribbon set at 1", ¾", out from face of blaze.
Power poles, etc., are nail and washer in face.
Building ties are to corner of foundation unless otherwise noted.

Statement of evidence relative to this corner location is on back of this page.

142/57

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Oliver 9/4/96
SIGNATURE DATE

Registration No. 8194

- Land Surveyor Professional Engineer
 County Surveyor County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of BENTON

I hereby certify that this document was filed in the Register of Deeds office at _____ M. on the _____ day of _____ A.D., 19 _____
Register of Deeds _____
By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

STATEMENT OF EVIDENCE:

East Quarter Corner of Section 25, T. 37, R. 28, Benton Co., MN.

West Quarter Corner of Section 30, T. 37, R. 27, Mille Lacs Co., MN.

The line between Ranges 27 & 28, T. 37, was run by Dep. Surveyor Theo. Conkey in Oct. 1849. We were unable to find any remnants of his* monument or accessories for this corner.

*Please see the Certificate Of Location for the NE corner of Section 1, T. 37, R. 28, Benton County; also being the NW corner of Sec. 6, T. 37, R. 27, Mille Lacs County; for a "discussion" regarding general conditions (including GLO resurveys and "Judicial Roads") affecting the locations of the corners along this County line.

In 1994 we were hired by Benton Co. to restore certain corners along their east Co. line. Old survey notes, subsequent to the GLO notes, from both counties, if any, are as follows (in chronological order):

Benton: Requested from the Co. Hwy. Dept.. None provided other than GLO notes.

Mille Lacs: None along this line other than GLO.

We are aware of no other surveys by others other than: In 1994 Comstock & Davis, Inc., via their Little Falls office, was hired to provide Benton County with geodetic coordinates on selected corners within the County. They did this with a combination of GPS and traditional methods. The subject corner was not restored during said survey.

After thorough and careful analysis we restored this corner by SPM along the straight line between the restored NW and SW corners of said Sec. 30. Because there was no record of subsequent monuments we did not excavate.

On 7/23/96 we placed a 3/4" iron pipe as shown on the front hereof.

MLCLS: /WQ303727

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON
Oct 3 8 49 AM '97
ALICE G. ENGELMEYER
COUNTY RECORDER
BY *A. Engelmeier* DEPUTY
X/m

244630