

1-19

A 356657

Certified, Filed and or Recorded on
Apr. 18, 2008 AT 12:21PM


Signed: CK
MARILYN J NOVAK GSV
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 10, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 1-29-07 found a 1/2" open iron pipe
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature: Jerome C. Wettstock Date: 16 April 2008 License No. 19552
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:

L103

East Quarter Corner of Section 10, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post was set at this location and bearing trees were recorded.

6" Blk Oak	S 60 W	104 links
6" Blk Oak	S 28 1/4 E	170 links

1961 M. W. Carley ties:

PP	NE	34.8
TP	NW	56.8

1982 David Regan, LS 12236, found a ¾ " iron pipe in center of north-south road and replaced pipe with a Benton County cast iron monument. Filed Certificate of Location (Doc. No. 162591)

2005 Certificate of Survey by William Lunser, LS 9394, shows the corner being 2682.30 feet north of the SW corner of Section 11.

2007 Westwood Professional Services, Inc. found a 1/2" open iron pipe in the centerline of a north-south road. New reference ties were created. The iron fits Mr. Lunser's distance to the south within 0.1 feet and fits a split of the distance between section corners within approximately 0.5 feet. A fence line to the east at the north sixteenth fits a split within approximately 5 feet of a split. I accepted the 1/2" iron pipe as marking the corner position.

County Coordinates obtained by GPS
 NAD 83 (1996 Adjustment)
 N-124014.484
 E-500034.589

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter _____ Corner of Section 10, Township 36, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 6/21/82 found a 3/4 inch iron pipe in center line of north-south County road
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 6/21/82 placed a Benton County cast iron monument
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David G. Ryan 7/13/82
SIGNATURE DATE

Registration No. 12236

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS ~~County Deeds~~
 County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 10 A.M. on the 27th day of July A.D., 19 82

Register of Deeds F.C. Johnson
County Recorder

By _____, Deputy

DOCUMENT NO. 162591