

295393

Office of the County Recorder, BENTON County, Minnesota
I hereby certify that the within Instrument was filed for record in this office on the 12th day of February, 2003, at 2:52 P.M.

Marilyn J. Novak
COUNTY RECORDER - Marilyn J. Novak

By _____ Deputy.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 32, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 11/05/01 found a 1/2" Solid Pin over a 1/2" Solid Pin
DATE

left monument as found lowered monument removed monument (explain)

On 11/05/01 placed a Cast Iron Monument in the location of the upper
DATE
1/2" Solid Pin and over the lower 1/2" Solid Pin



Ref. Job #20015163

Ties that are found and in good condition are noted as 'existing'. New tree and power pole ties are to the head of a nail with a brass disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Angie A. Allen Date 2/10/03 License No. 12684

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

L323

The East Quarter Corner of Section 32, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Edwin James Jr. set a wood post at this location and bearing trees were recorded.
4" Blk. Oak N 15 E 828 links

Undated The County Surveyors records in Book 1, page 223, refer to the corner with the following ties.

T.P. NW 49.1
G.P. SW 44.05

193? Elletson notes the following ties.

T.P. SW 41.0
T.P. NW 52.04

2001 Westwood Professional Services, Inc. found a 1/2" solid pin over a 1/2" solid pin. Removed the top 1/2" solid pin and set a cast iron monument over the lower 1/2" solid pin and established new reference ties.

2003 Westwood Professional Services, Inc. found a cast iron monument at the corner and located it using GPS.

County Coordinates Obtained by GPS (Cast Iron Monument-2001)
NAD 83 (1996 Adjustment)
N-102724.177
E-489744.784

County Coordinates Obtained by GPS (Cast Iron Monument)(1/13/03)
NAD 83 (1996 Adjustment)
N-102724.235
E-489744.775