

Certified, Filed and or Recorded on
Sep. 22, 2009 AT 12:20PM


Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER
Fee Amount: \$46.00

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 14, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09-09-09 found a 1/2 inch Iron Pipe down 0.2'
DATE on centerline of 35th St. NE and 22' west of center of Driveway No. 6012
- left monument as found lowered monument removed monument (explain)
- On _____ placed a _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Kevin J. Metz Date 9-14-2009 License No. 40343
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer
MNDOT

Statement of Evidence:**North Quarter Corner of Section 14, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.**

1852 Original General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.

6" Bur Oak	S 17 E	317 links
5" Aspen	N 72 W	34 links

1961 M.W. Carley ties:

TP	N	39.25
12" Poplar	S	58.45
6" Poplar	SW	75.15

2002 No other survey records were found on this corner in the Benton County records.

2005 Certificate of Survey by William Lunser, LS 9394, shows an iron monument at the corner 2660.48 feet east of the Southwest Corner of Section 11.

2005 A Minnesota Department of Transportation survey crew found an iron pipe that fit occupation of east-west road and fence line north. Measured 2652.56 feet to the Northeast Corner of Section 14 and 2660.45 feet to the Northwest Corner of Section 14.

County Coordinates obtained by GPS (for reference only):

NAD 83 (1996 Adjustment)

N- 121281.175

E- 502741.843

2009 On September 9th, 2009, The Minnesota Department of Transportation found a ½" iron pipe. Reference ties were established as shown on the front of this document. The Minnesota Department of Transportation accepts the ½" iron pipe as the correct location of the North Quarter Corner of Section 14.

For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.