

Certified, Filed and or Recorded on  
Feb. 12, 2010 AT 12:54PM


Signed: M  
MARILYN J NOVAK G V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 18, Township 36, Range 30  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 11/30/09 found a 1/2" IRON PIPE 1 FOOT WEST OF NORTH/SOUTH FENCELINE  
AND 42 FEET SOUTH OF FENCELINE WEST
- left monument as found       lowered monument       removed monument (explain)
- On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock  
Benton County Surveyor  
License No. 19552

Date: 02/05/2010

**Statement of Evidence:****L181**

The North Quarter Corner of Section 18, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey established this corner and set a wood post at the corner location with bearing trees marked:
- |             |        |           |
|-------------|--------|-----------|
| 12" Bur Oak | S 75 W | 360 links |
| 15" Bur Oak | N 62 E | 152 links |
- 1980 Paul Wellen, LS 10461, set an iron monument for the corner. Notes do not show how corner was determined or set.
- 2002 Westwood Professional Services, Inc. found a ½ " iron pipe 1-foot west of a fence line north. The pipe was found to be 24.3 feet north and 6.0 feet east of the lost position between section corners.  
 County Coordinates obtained by Side-tie  
 NAD 83 (1996 Adjustment)  
 N- 121341.044  
 E- 481478.738
- 2009 Westwood Professional Services, Inc. found a ½" iron pipe 2,860.00 feet from the NW corner of Section 18 and 2,654.90 feet from the NE corner of Section 18. The ½" iron pipe is in agreement with the position reported in 2002. Reference ties were established.
- County Coordinates  
 NAD 83 (1996 Adjustment)  
 N- 121341.044  
 E- 481478.738