

Certified, Filed and or Recorded on
Oct. 31, 2008 AT 08:35AM


Signed: *MJ*
MARILYN J NOVAK B V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 8, Township 36, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-5-08 found a CAST IRON MON
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Ch. Hyl*
Deputy County Surveyor
License No. 43932

Date: 10/14/08

Benton County Surveyor's Office
 Chris Hoglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

K082

Northeast Corner of Section 8, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original General Land Office survey established this corner set a wood post at this location and bearing trees were recorded.

7" Poplar	S 17 1/2 E	22 links
5" Blk Oak	N 39 W	26 links

1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by hub set in the center of road with fence lines east and west. Ties are the same as listed in County Surveyor's Record Book 1, page 99:

12" R Oak	NW	117.15
12" W Oak	NW	132.2

2003 Barry Dorniden, LS 23044, reported establishing the corner in center of road on fence line west.

2004 MN/DOT found 1/2" iron pipe with cap No. 23044.
 County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N- 126993.274
 E- 521515.227

2008 Westwood Professional Services, Inc. found a CIM. CIM is accepted as marking the obliterated corner position. Coordinates obtained by RTK GPS coincide with 2004 MN/DOT position. Ties are shown on the front of this certificate.

Certified, Filed and or Recorded on
Sep. 23, 2008 AT 01:31PM


Signed: BW
MARILYN J NOVAK G V
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 8, Township 36, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-5-08 found a CAST IRON MON.
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 8/29/08

Benton County Surveyor's Office
 Chris Høglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

K082

Northeast Corner of Section 8, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original General Land Office survey established this corner set a wood post at this location and bearing trees were recorded.
- | | | |
|------------|------------|----------|
| 7" Poplar | S 17 1/2 E | 22 links |
| 5" Blk Oak | N 39 W | 26 links |
- 1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by hub set in the center of road with fence lines east and west. Ties are the same as listed in County Surveyor's Record Book 1, page 99:
- | | | |
|-----------|----|--------|
| 12" R Oak | NW | 117.15 |
| 12" W Oak | NW | 132.2 |
- 2003 Barry Dorniden, LS 23044, reported establishing the corner in center of road on fence line west.
- 2004 MN/DOT found 1/2" iron pipe with cap No. 23044.
 County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N- 126993.274
 E- 521515.227
- 2008 Westwood Professional Services, Inc. found CIM in place of 1/2" iron pipe set in 2003. Coordinates obtained by RTK GPS coincide with MN/DOT position. Ties are shown on the front of this certificate.