

Certified, Filed and or Recorded on
Oct. 31, 2008 AT 08:29AM

Signed: [Signature]
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARTIN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 4, Township 37, Range 31
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 8-27-08 found a 2" OPEN IP


left monument as found lowered monument removed monument (explain)

On _____ placed an _____

FIELD

FIELD

33
4



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature: [Signature]
Deputy County Surveyor
License No. 43932

Date: 10/14/08

Statement of Evidence:

F041

North Quarter Corner of Section 4, Township 37 North, Range 31 West, Watab Township, 4th Principal Meridian, Benton County, Minnesota.


- 1849 Original US General Land Office survey set a wood post in a mound with a pit 6 links east for the corner location.
- 1945 MN/DOT right of way and alignment map for US 10 shows corner assumed in center of north-south trail in line with field divisions east-west. Found concrete corner post lying above ground. Map gives distance of 643.5 feet east to centerline of south bound US 10 and a distance of 2684.2 feet to the NE corner of Section 4, assumed at road intersection.
- 1972 William Lunser, LS 9394, found a broken concrete monument as shown on Minn. Hwy R/W map. He set a 2" iron pie at the location and filed a Certificate of Location (#133439). He notes a distance of 2677.34 feet to the NE Corner of Sec 4 and a distance of 2677.29 feet to the NW Corner of Sec. 4.
- 2002 Westwood Professional Services, Inc. found 2" iron pipe per Lunser's certificate with ties to 2 pine trees to the southeast checking. We measured 2677.74 feet to the NE corner and 2677.39 feet to the NW corner of Section 4.
County Coordinates Obtained by GPS to 2" Iron Pipe
NAD 83 (1996 Adjustment)
N-164266.272
E-460126.370
- 2004 MN/DOT
County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-164266.385
E-460126.358
- 2008 Westwood Professional Services, Inc. found a CIM at the corner location. CIM is accepted as marking the obliterated corner position. County Coordinates Obtained by GPS coincide with 2004 MN/DOT position.

Watab

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 25 day of August, 1972
I did restore the north quarter corner of Section 4,
Twp. 37, Rg. 31, Benton County, Minnesota, which
was evidenced by a broken conc. monument as shown on Minn.
High. R/W map.

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of a 2" iron pipe and that
I did establish witness or reference monuments as shown below:



I hereby certify that the
above is true and correct
and that I am a registered
Land Surveyor under the laws
of the State of Minnesota.

William J. Jensen

Minn. Registration No. 9394

Office of the Register of Deeds,
Benton County, Minn.

I hereby certify that the within
instrument was filed for record
in this office on the 9th day of
February, 1973.

J. A. Johnson
Register of Deeds

By Marilyn Novak Deputy.