COUNTY RECORDER

	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
Noe	
4TH	Range , rownship , Range
At the	e corner location shown on the sketch:
X	DATE Found a CIM
X	left monument as found lowered monument removed monument (explain) On of APRIL 08 placed an PK NAIL & COUNTY WASHER OVER FOUND CIM
•	
——————————————————————————————————————	SPIKE IN IH" PINE
Strationage	35.39 SPIKE IN 14" PINE
	PKNAIL
	21 24 34 35
	Statement of evidence for this corner location is on back of this page,
I hereby and that	certify that this document was researched and prepared by me or under my direct supervision I am a licensed Land Surveyor under the laws of the State of Minnesota.
Signature Title:	Land Surveyor Professional Engineer County Surveyor County Engineer

PAGE / OF 2

Benton County Surveyor's Office Jerome C. Wittstock, County Surveyor Minnesota License No. 19552

Statement of Evidence:

L342

Northeast Corner of Section 34, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

Original US General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded.

8" Bur Oak

S 16 1/4 W

563 links

8" Bur Oak

N 44 W

371 links

1977 Paul Wellen, LS 10461, found a 1/2" pipe at the corner location and filed a Certificate of Location (#147249).

1992 County Coordinates from MN/DOT to 3/4" iron pin:

NAD 83 (1986 Adjustment)

N-105370.768

E-500329.926

1995 County ties show found a 3/4" pin at the corner.

Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a ½ "iron pin:

N-105371.033

E- 500329.888

2003 Westwood Professional Services, Inc. found corner marked by a cast iron monument. Do not know who set the CIM, but it agrees with Wellen's position and the coordinates determined by Comstock and Davis.

County Coordinates by GPS to a found CIM.

NAD 83 (1996 Adjustment)

N-105371.091

E-500329.340

2008 Westwood Professional Services, Inc. verified the 2003 coordinates, established reference ties and placed a PK nail and county washer flush with bituminous surface over existing CIM.

CERTIFICATE OF LOCATION Southwest Corner of Section 26	OF GOVERNMENT CORNER,Township 36N,Range 30W,4th _P.M.
STATE OF MINNESOTA, County of Benton	
At the corner location shown on the sketch:	n Diana
\bullet On $\frac{9-12-77}{\text{DATE}}$ found a $\frac{1/2 \text{ "iro}}{\text{iro}}$	n ripe
☑ left monument as found, ☐ lowere	ed monument, 🗆 removed monument (explain)
□ Onplaced a	
SKETCH OF RI	FERENCE TIES
1	
4	
- NI-	•
Refer to ment page	
	•
Statement of evidence relative to this corner lo	cation is on back of page. 147249
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS County of Benton
contained herein was prepared by me or under my direct supervision.	County of
	I hereby certify that this document was filed in the Rea of Deeds office at 4 P: .M. on the
Paul E. Wellen 1/9/78	the Reg. of Deeds office at 4 P: .M. on the 10th day of January A.D., 19 78
Registration No. 10461	Register of Deeds F.A. Johnskn
■ Land Surveyor, □ Professional Engineer	By A. E. ,Deputy
	DOCUMENT NO.
☐ County Surveyor, ☐ County Engineer	

1	n	ч	۵	v	f	M	o.	
1	11	u	ㄷ	х	- 1	v	v.	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
SOUTHWEST Corner of Section 26, Township 36N, Range 30W, 4TH P.M.
STATE OF MINNESOTA, County of BENTON
At the corner location shown on the sketch:
On 9-12-77 found a 1/2" IRON DIPE
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)
Onplaced a
SKETCH OF REFERENCE TIES
4
₄ 40.29
4"NORWAY PINE
POWER POLE
36.31/ N.W. CORNER
1/2 STORY
HOUSE
\[\lambda \]
Ó
£.
Statement of suidence relative to this corner longtion is on back of page
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under County of
the Reg. of Deeds office at M. on the
Registration No. 1046/ Register of Deeds 1.0. (1978)
Registration No. 1046 Register of Deeds
☐ County Surveyor, ☐ County Engineer ☐ DOCUMENT NO

Found a $\frac{1}{2}$ inch iron pipe at the intersection of a north-south township road and a fence line east.

NMENT CORNER
,Range <u>30</u> ,P.M.
removed monument (explain)
R30
of page.
REGISTER OF DEEDS
REGISTER OF DEEDS
REGISTER OF DEEDS hat this document was filed in office atM. on the
REGISTER OF DEEDS hat this document was filed in office atM. on the A.D., 19
REGISTER OF DEEDS hat this document was filed in office atM. on the

		·	