

Certified, Filed and or Recorded on
Nov. 04, 2008 AT 12:35PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 28, Township 38, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-30-08 found a 1/2" IRON PIPE # 12236

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Benton County Surveyor's Office
 Chris Hoglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:**B281**

North Quarter Corner of Section 28, Township 38 North, Range 29 West, Alberta Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded:
- | | | |
|-------------|--------|----------|
| 10" W Birch | S 18 E | 15 links |
| 10" Poplar | N 75 W | 15 links |
- 2002 No resurvey information was found on this corner in the Benton County records.
- 2004 Certificate of Survey by David Regan, LS 12236, shows an iron pipe set at the corner with a distance of 5330.71 feet to the North $\frac{1}{4}$ corner of Section 21.
- 2008 Westwood Professional Services, Inc. found a $\frac{1}{2}$ " iron pipe capped 12236 at the intersection of 135th St. NE and a fence line north. Measured 2611.13 feet to the NW corner and 2612.44 feet to the NE corner of Section 28. Position falls 5.83 feet south and 0.65 feet west of lost position. Township road and fence line occupation appear to be longstanding evidence of section line location. Iron pipe is accepted as marking the obliterated position for this corner.
 County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-175017.510
 E-524003.252