

Certified, Filed and or Recorded on
Nov. 06, 2008 AT 08:41AM


Signed: CK
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 36, Township 37N, Range 29W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On _____ found a _____
- left monument as found lowered monument removed monument (explain)
- On 23 OCT 2008 placed on PK NAIL & BENTON COUNTY BRASS DISC



25
36



* CORNER FALLS 1.0' +/- N OF Q.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oleg
Deputy Benton County Surveyor
License No. 45872

Date: 11/04/2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872
 Page 1 of 2

Statement of Evidence:**H361**

North Quarter Corner of Section 36, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

This corner is noted on the following recorded plats

<i>COUNTY AUDITOR PLAT</i>	12/21/1906	<i>Felix Parent</i>
<i>EASTVIEW MEADOWS TWO (CIM)</i>	6/26/1996	<i>Sidney Williamson</i>

- 1855 Original US General Land Office survey set a wood post with bearing trees noted as:
- | | | |
|------------|----------|----------|
| 9" Blk Ash | S 23 ½ W | 38 links |
| 12" Linden | N 16 ½ E | 13 links |
- 1912 County Engineer's Notebook 1, pages 37 to 42, contains a survey for SR No. 10 by M. J. Cleveland. Notes show road run east-west and crossing ¼ line 2647 feet east of the NW corner of Section 36.
- 1925 County Engineer's Notebook 44 shows distance of 2640.6 feet from the NW corner of Section 36 with ties:
- | | | |
|------|----|--------|
| T.P. | NW | 60.5' |
| T.P. | SW | 103.0' |
- 1938 County Engineer's Notebook 113 contains survey for SAR 4 running east to west. Notes show corner as a granite monument in road and in line with fences north and south. Ties:
- | | | |
|----------------|----|------|
| 8" W Oak | NE | 45.1 |
| 8" Twin Cherry | SE | 44.1 |
- Stationing gives distances of 2647.6 to the NE corner and 2640.0 feet to the NW corner with a delta angle of 0-46' left.
 (Notation in 1956 shows ½" rod placed over granite monument.)
- 1956 County Surveyor's Record Book 1, pages 509 and 531. Reference ties to an iron over a granite monument are noted as:
- | | | |
|----------------|----|---------------|
| TP | NE | 57.6 |
| 18" Elm | NE | 35.15 |
| 8" W Oak | NE | 45.1 (Older) |
| TP | NW | 60.5 (Older) |
| TP | SW | 103.0 (Older) |
| 8" Twin Cherry | SE | 44.1 (Older) |
- 1968 County reference ties:
- | | | |
|---------------|----|------|
| PP | SW | 57.3 |
| E-end Culvert | S | 22.5 |
- 1988 Benton County Highway Department notes a ¾" pipe set over a granite monument.
- 1990 Michael Trunk, LS 18434, set a cast iron monument based on tie to PP SW 57.58 feet and highway stationing and filed a Certificate of Location (#199671).
- 2001 Westwood Professional Services, Inc. found a cast iron monument at the centerline of an east/west road.

Benton County Surveyor's Office
Jason W. Oberg, Deputy County Surveyor
Minnesota License No. 45872
Page 2 of 2

- 2008 The County Surveyor's Office searched and found the tie to the PP as reported in 1968 (Meas. 57.60 ft. vs. Rec. 57.3 ft.), and ties to the Right-Of-Way sign posts to the north and south. The position gives distances to the NW corner and NE corner as 2639.76 feet and 2648.36 feet respectively, which agrees with the distance to the NW corner reported in 1925 as 2640.6 feet and the distance reported to the NE corner reported in 1938 as 2647.6 feet. It appears that Trunk recovered the granite stone position in 1990 by locating his monument from the PP tie circa 1968. The Surveyor accepts the position as marking the CIM set by Trunk in 1990 as perpetuating the obliterated position. The Surveyor set a PK nail with a Benton County disk flush with the surface of an east-west bituminous road (C.S.A.H. No. 4). Ties were updated.

County Coordinates to PK nail by GPS
NAD 83 (1996 Adjustment)
N-137708.217
E-539748.319

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


N¹/₄ Corner of Section 36, Township 37 N, Range 29 W, 4TH P.M.

STATE OF MINNESOTA, County of BENTON

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 10-1-90 placed a BENTON CO. HWY. DEPT. CAST IRON MONUMENT
DATE
FLUSH WITH ROADWAY AND ESTABLISHED 4 REFERENCE TIES AS SHOWN.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Michael J. Trank 10-3-90
SIGNATURE DATE

Registration No. 18434

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

N $\frac{1}{4}$ CORNER OF SECTION 36, TOWNSHIP 37, RANGE 29

- 1) A post was set by U.S. Government Surveyors in July of 1855. No evidence of the post or Bearing trees remain.
- 2) The Benton Co. Highway Dept. records indicate a 3/4" iron pipe was found on 4-26-88 which was reportedly set over a granite monument and ties to the iron pipe were made.
- 3) During a survey that was done by me in the SW $\frac{1}{4}$ of the NE $\frac{1}{4}$ of Sec. 25, T.37, R.29 in Sept. of 1990 I reset a traverse station at this point per the Benton Co. Hwy. Dept. ties of 4-26-88 which consisted of the nail & disc in the power pole 57.58 feet away and at a distance of 2639.68 feet East of the NW corner of Sec. 36. This position fit well with the assumed NW corner of the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 36 and since there was evidence that the iron pipe located by the Benton Co. Hwy. Dept. was placed over a granite monument this position was accepted by me.

1 9 9 6 7 1

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

OCT 4 1 57 PM '90

ALICE G. ENGELMEYER
COUNTY RECORDER

BY Jed DEPUTY