

MARILYN J. NOVAK  
COUNTY RECORDER

BY CK DEPUTY

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON

293716

2002 DEC 31 P 3:55


### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 19, Township 36, Range 28

4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE
- left monument as found     lowered monument     removed monument (explain)
- On 12/4/2002 placed an 1/2" iron pipe capped #12684 at the lost position  
DATE



New ties are to the head of a nail.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Gay A. Aker Date 12/12/02 License No. 12684

Title:  Land Surveyor     Professional Engineer     County Surveyor     County Engineer

Statement of Evidence

J193

The East Quarter Corner of Section 19, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Corner established by GLO surveyor Oscar F. Davis and marked by a wood post with bearing trees recorded as:

5" Poplar	N 14 E	28 links
3" Oak	S 60 W	6 links
5" Poplar	S 1 E	14 links

1915 The County Surveyors records in Book 1, page 45, shows that on June 1, 1915, J.P. Soderstrum did a survey of Section 19. He set the corner by lost methods on line and midway between the section corners. He measured 80.54 chains (5,316.64 feet) between section corners and set a wood stake for the corner. He notes a fence line from the west 0.07 chains (4.62 feet) north of where he set the corner and that residents claim the fence line is at the 1/4 line, according to a stake set by Parent in 1889. However, Parents notes show corner set lost and claims to have ignored the fence line and therefore Soderstrum also did.

2002 Westwood Professional Services, Inc. searched corner area at intersection of roads north, south, and east and fence line west. No monument was found. We measured 5318.80 feet between section corners, which compared well with Soderstrum. The lost position fits the occupation of roads and fence line. On December 4, 2002 Westwood Professional Services, Inc. set an iron capped #12684 at the lost position, as J.P. Soderstrum did in 1915.

County Coordinates

NAD 83 (1996 Adjustment)

N-113684.408

E-547974.679