

1-6

A 362862

Certified, Filed and or Recorded on  
JAN. 06, 2009 AT 02:56PM

Signed: CK  
MARILYN J NOVAK 6 V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 33, Township 36N, Range 28W  
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 6/10/2005 found a EXCAVATED A 2.5' WIDE BY 8' LONG BY 5' DEEP HOLE,  
DATE  
FOUND NOTHING

left monument as found  lowered monument  removed monument (explain)

On 6/29/2005 placed a BENTON COUNTY CAST IRON MONUMENT, DOWN 0.1 FEET.  
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Sam J. Deho Date 8-13-2008 License No. 40341

Title:  Land Surveyor  Professional Engineer  County Surveyor  County Engineer

**Statement of Evidence:**

J333

East Quarter Corner of Section 33, Township 36 North, Range 28 West, Glendorado Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- |             |        |           |
|-------------|--------|-----------|
| 12" Bur Oak | N 41 W | 103 links |
| 7" Blk Oak  | N 9 E  | 79 links  |
- 1935 County Engineer's Notebook No. 92 contains survey for SAR No. 7 running north to south. Notes corner as a hub. Ties:
- |        |       |        |        |
|--------|-------|--------|--------|
| Hub SE | 45.1' | Hub NE | 43.65' |
|--------|-------|--------|--------|
- Stationing gives distances of 2656.5 feet to the NE corner and 2642.8 feet to the SE corner with a delta angle of 0-18' left.
- 2005 Sam DeLeo, LS 40341, excavated a hole that measures 8 feet long by 2.5 feet wide by 5 feet deep at a position determined using the 1935 measurements from the corresponding section corners to the north and south. No evidence of a monument that marked the corner was found. A standard cast iron monument was set at the obliterated position based on the 1934 records and reference ties were recorded.

County Coordinates to set corner:  
 NAD 83 (1996 Adjustment)  
 N- 103004.963  
 E- 558540.292