

A 362575

Certified, Filed and or Recorded on
Dec. 24, 2008 AT 08:54AM

Signed: BW
MARILYN J NOVAK 6 V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 4, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-14-08 found a BROKEN CAST IRON MONUMENT

left monument as found lowered monument removed monument (explain)

On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 12/17/08

Benton County Surveyor's Office
 Chris Høglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

C043

East Quarter Corner of Section 4, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office set a wood post at this location and bearing trees were recorded:

5" Blk Oak	S 13 E	105 links
4" Blk Oak	S 27 W	235 links

1908 County Surveyor's Record Book 2, page 164, M.J. Cleveland notes he set the corner lost with distances of 40.76 chains (2690.16 feet) to the NE corner Sec 4 and 40.95 chains (2702.70 feet) to the SE corner Sec 4. Ties:

12" Blk Oak	N 35-15 W	19 links
-------------	-----------	----------

1984 Paul Wellen, LS 10461, set a cast iron monument at the centerline of roads north/south and a tree line east/west. He filed a Certificate of Location (#173404). Measured 2678.97 feet to the SE corner.

2008 Westwood Professional Services, Inc. found a CIM fitting 1984 Wellen ties. Measured 2678.93 feet to the SE corner and 2709.14 feet to the NE corner of section 4. Location fits longstanding occupation along the east/west quarter lines of Section 3 and 4. CIM is accepted as marking the obliterated position for this corner.

Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-193735.877
 E-494124.336

10/27/2008

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 4, Township 38, Range 30, 4th P.M.

STATE OF MINNESOTA, County of BENTON

At the corner location shown on the sketch:


On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

~~XXX~~ On 8-16-84 placed a CAST IRON MONUMENT
DATE

Handwritten notes:
found
monument
8-16-84
cast iron
monument

SKETCH OF REFERENCE TIES



173404

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision

Dan J. Allen 11/7/85
SIGNATURE DATE

Registration No. 10461

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Benton

I hereby certify that this document was filed in the Co. Recorders office at 11:00 A.M. on the 11 day of May A.D., 19 85

County Recorder Alice C. Engelmeier

By NO, Deputy

DOCUMENT NO. _____

Statement of Evidence:

East Quarter corner, Section 4, T38N, R30W, 4th P.M.

During th G.L.O. Survey of 1852, a wooden post was set to mark this corner.

In 1984, Paul E. Wellen, L.L.S., St. Cloud, Minnesota, set a Cast Iron Monument the intersection of the center line of a north-south township road and tree lines east and west.