

Certified, Filed and or Recorded on
Nov. 04, 2008 AT 01:16PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 9, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-14-08 found a 1/2" I.P. # 1955Z

left monument as found lowered monument removed monument (explain)

On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Statement of Evidence:

C093

East Quarter Corner of Section 9, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office set a wood post at this location and bearing trees were recorded:
- | | | |
|-----------|------------|----------|
| 12" Aspen | S 86 1/2 E | 5 links |
| 12" Aspen | N 86 1/2 W | 13 links |
- 2002 No resurvey information was found on this corner in the Benton County records.
- 2007 Jerome C. Wittstock, Westwood Professional Services, Inc. - The corner was excavated and no corner evidence was found. A 10-foot east-west by 10-foot north-south x 4-foot deep hole was dug to original soil where corduroy was also found. The excavation was centered on the fence to the west and the north-south centerline of the gravel road. 1/2" x 14" iron pipe capped 19552 was set at centerline of north/south road and fence line to west.
- 2008 Westwood Professional Services, Inc. found an iron pipe capped 19552 in the centerline of 45th Ave NE and a fence line running west. Measured 2720.77 feet to the NE corner and 2659.36 feet to the SE corner of section 9. Iron pipe capped 19552 is accepted as marking the obliterated position for this corner.
 Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-188339.958
 E-494322.351