

A 361598

Certified, Filed and or Recorded on
Nov. 06, 2008 AT 08:48AM


Signed: OK
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 34, Township 30N, Range 28W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/16/08 found a 1/2" IRON PIPE DOWN 0.15'
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oly
Deputy Benton County Surveyor
License No. 45872

Date: 11/03/2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:

A343

The East Quarter Corner of Section 34, Township 38 North, Range 28 West, Granite Ledge Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|-----------|--------|----------|
| 9" Pine | S 30 W | 25 links |
| 12" Sugar | N 55 E | 20 links |
- 2002 No resurvey information was found on this corner in the Benton County records.
- 2003 Westwood Professional Services, Inc. searched corner area and found no evidence of a monument. The lost position fit the center of north-south gravel road and occupation fence lines east and west. Measured 5237.26 feet between section corners and determined lost position midway and on line between section corners. On 9/24/03 an iron pipe with cap No. 41886 (Lee Brown) was set at the lost position.
 County Coordinates to lost position:
 NAD 83 (1996 Adjustment)
 N- 166995.804
 E- 562996.367
- 2008 The County Surveyor's Office searched and found a 1/2" iron pipe under the centerline of a north-south gravel road on line with old tree lines to the east and west. Position fits the lost position as reported by Westwood Professional Services, Inc. in 2003, and is accepted as the best evidence. The Surveyor made ties and coordinates obtained by GPS agree with those reported by Westwood in 2003, above.