

Certified, Filed and or Recorded on
Dec. 24, 2008 AT 08:45AM

Signed: BW
MARILYN J NOVAK
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 6, Township 37N, Range 30W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10/30/08 found a 1/2" OPEN IRON PIPE DOWN 0.4'

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jean W. Oley
Deputy Benton County Surveyor
License No. 45872

Date: 12/09/2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:**G063**

East Quarter Corner of Section 6, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.

10" Blk Oak S 74 1/2 W 277 links

1923 County Engineer's Notebook No. 40 contains a survey for CAR No. 1 running south to north. Notes corner marked by an iron with ties:

3" Oak SE 39.9'
 Stake W 33'

Stationing gives distances of 2712.0 feet to the SE corner and 2826.4 feet to the NE corner with a deflection angle of 0-10' left (running south to north).

County Surveyor's Record Book 1, page 397, notes the same ties.

1938 County Engineer's Notebook No. 116 contains a survey for SAR No. 1 that notes the following ties to a spike in road:

2" Oak NE 33.8
 2" Oak SE 42.9

Stationing gives distances of 2712.2 feet to the SE corner and 2828.1 feet to the SE corner with a deflection angle of 0-10' left (running south to north).

1977 County Engineer's ties:

4" Boxelder NE 76.95
 4" Boxelder E 77.15
 PP SE 74.25
 Bolt in Steel Post W 127.44

2007 Westwood Professional Services Inc. found a 1/2" open iron at the centerline of road north/south.

2008 The County Surveyor's Office searched and found a 1/2" open pipe 0.8 ft. east of centerline and down 0.4 ft. in the bituminous in CSAH No. 1. Measurements to the NE and SE Corners of Sec. 6 give 2834.37 ft. and 2705.24 ft, respectively, and the deflection angle measured going south to north measures 0°14'42" left, which reasonably agree with 1923 and 1938 measurements. The 1/2" monument also fits with the Bolt in Steel Post tie from 1977 (meas. 127.54 ft.). The pipe is accepted as marking the best evidence and ties were made.

County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N- 161492.331
 E- 484406.102