

MARILYN J. NOVAK
COUNTY RECORDER
BY Marilyn J. Novak DEPUTY

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

291184

2002 OCT 30 P 3: 22

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 23, Township 37, Range 28
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 9/30/02 found a 1/2" SOLID IRON PIN DOWN 1.5 FEET
DATE


left monument as found lowered monument removed monument (explain)

On 10/8/02 placed a CAST IRON MONUMENT OVER IRON PIN
DATE

FD NAIL - DISC IN
CUT OFF BRACE POLE
49.98

CSAH 9

SPK IN
PP UP 6.0
45.43'



GRAVEL

85TH STREET NE

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Gay H. Aker* Date 10/14/02 License No. 12684

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

I232

The Northeast Corner of Section 23, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 US General Land Office survey established this corner and set a wood post and bearing trees were recorded as follows:

12" Tamarac	N 50 E	55 links
12" Tamarac	S 68 ½ E	64 links

1960 County Highway Department notes show "found old stake, placed iron over stake" with the following ties:

1963 County Highway Department list the following ties:

PP	NE	41.3
Anchor Pole	NW	50.8
TP	SW	40.05

2002 On 9/30/02, Westwood Professional Services, Inc. found a ½ " solid iron pin down 1.5 feet in the intersection of the centerlines of County Road 9 (running north and south) and 85th Street NE (running east and west). Only one 1963 tie remained; the Anchor Pole to the NW and it checked reasonably well. The pole has been cut off and is leaning slightly to the east. Accepted the found iron pin as being the best evidence of the obliterated corner position based on the 1960 notes.

On 10/8/02, Westwood Professional Services, Inc. set a cast iron monument over the found iron pin and took ties.