

MARILYN J. NOVAK
COUNTY RECORDER
BY Marilyn J. Novak DEPUTY

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

295388


2003 FEB 12 P 2:51

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 18, Township 36, Range 29
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

- On 11/21/01 found a pointed wood post. lying down
DATE
- left monument as found lowered monument removed monument (explain)
- On 12/07/01 placed a cast iron monument
DATE



New ties are to the head of a nail with a disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature] Date 2/10/03 License No. 12684

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

K181

The North Quarter Corner of Section 18, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Oscar F. Davis set a wood post at this location and bearing trees were recorded.

5" Aspen	N 65 E	186 links
4" B. Oak	N 81 E	175 links

2001 Westwood Professional Services, Inc. found a pointed wood post laying flat, buried under a flat post, in a swampy area. The post falls on the extension of an old barbwire fence (running west), a tree line (running north) and an old trail (running south).

A 20" Double R Oak fits original BT distance and bearing. Do not believe that oak is the original BT, but believe it is highly likely that the current tree grew from the stump of the original BT. Accepted this corner as a perpetuated original corner. The position also fits the GLO notes that call for the corner being in a willow marsh.

Westwood Professional Services, Inc. accepted the position of the wood post as the location for the corner. We removed the pointed wood post and set a cast iron monument in its place and established reference ties. By accepting this as the corner position creates a north/south quarter line that matches a fence corner at the center of the section. Other fence lines, throughout the section, meander back and forth as much as +/- 15 feet.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-121658.360
E-513815.975