

Certified, Filed and or Recorded on
Oct. 31, 2008 AT 08:32AM


Signed: M
MARILYN J NOVAK G V 4
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 18, Township 36, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-5-08 found a CAST IRON MON
- left monument as found lowered monument removed monument (explain)
- On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 10/14/08

Benton County Surveyor's Office
 Chris Hogleund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:**K182**

Northeast Corner of Section 18, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post and bearing trees were recorded:
- | | | |
|-------------|------------|-----------|
| 20" Bur Oak | S 86 1/2 E | 288 links |
| 10" Bur Oak | N 86 E | 375 links |
- 1966 County Highway Notebook No. 2, page 13, shows ties to an I.P.
- | | |
|----------|------|
| G.P. NE | 37.3 |
| Gate P.E | 33.5 |
- 2001 Westwood Professional Services, Inc. found a CIM at the corner. No record of the origin of the CIM.
- 2002 No record history found on this corner in the Benton County Surveyor records. Coordinates Obtained by GPS (For reference use only – 3rd order) (CIM)
 NAD 83 (1996 Adjustment)
 N-121727.366
 E-516482.673
- 2004 MN/DOT survey crew found CIM and obtained County Coordinates by GPS:
 NAD 83 (1996 Adjustment)
 N-121727.332
 E-516482.542
- 2008 Westwood Professional Services, Inc. found a CIM at the corner. 1966 ties no longer exist. CIM fits centerline of township road and fence lines east and west which are longstanding evidence of section lines. Coordinates obtained by RTK GPS coincide with 2004 MN/DOT position.

Certified, Filed and or Recorded on
Sep. 23, 2008 AT 01:32PM


Signed: BW
MARILYN J NOVAK 6 V 1
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 18, Township 36, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-5-08 found a CAST IRON MON
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 8/29/08

Benton County Surveyor's Office
 Chris Høglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:**K182**

Northeast Corner of Section 18, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post was set and bearing trees were recorded:

20" Bur Oak	S 86 1/2 E	288 links
10" Bur Oak	N 86 E	375 links

1966 County Highway Notebook No. 2, page 13, shows ties to an I.P.

G.P. NE	37.3
Gate P.E	33.5

2001 Westwood Professional Services, Inc. found a CIM at the corner. No record of the origin of the CIM.

2002 No record history found on this corner in the Benton County Surveyor records. Coordinates Obtained by GPS (For reference use only – 3rd order) (CIM)
 NAD 83 (1996 Adjustment)
 N-121727.366
 E-516482.673

2004 MN/DOT survey crew found CIM and obtained County Coordinates by GPS:
 NAD 83 (1996 Adjustment)
 N-121727.332
 E-516482.542

2008 Westwood Professional Services, Inc. found a CIM at the corner. 1966 ties no longer exist. CIM fits centerline of township road and fence lines east and west which are longstanding evidence of section lines. Coordinates obtained by RTK GPS coincide with 2004 MN/DOT position.