

Certified, Filed and or Recorded on
Nov. 04, 2008 AT 12:33PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH EAST Corner of Section 19, Township 38, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-29-08 found a BROKEN CAST IRON MONUMENT

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Ch. [Signature]*
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Benton County Surveyor's Office
 Chris Hogle, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:**B192**

Northeast Corner of Section 19, Township 38 North, Range 29 West, Alberta Township,
 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at the location and bearing tree was recorded.
- | | | |
|-----------|------------|----------|
| 12" Sugar | N 30 1/2 E | 12 links |
| 14" Sugar | N 1 1/2 W | 9 links |
- 1931 County Engineer's notebook No. 65 contains road survey for SAR No. 12 running west to east. Corner is shown as a hub with ties:
- | | | |
|-----------|----|-------|
| Box Elder | SW | 77.7' |
| 12" Oak | SW | 70.2' |
- (Ties also listed in County Surveyor's Record Book 2, page 274.)
- 1935 County Engineer's Notebook No. 93 contains survey for Road running from south to north. Notes corner a hub in SAR No. 12 running east and west. Same ties as in 1931.
- 1959 County Engineer's Notebook No. 220 contains a road survey for CSAH 12 running west to east on section line. Corner is shown marked by an iron in center of 4-way road intersection. Ties.
- | | | |
|-----------|----|--------|
| 15" Maple | SW | 133.3' |
| TP | NE | 50.3' |
- Also shows same ties as below in 1967.
- 1964 County Engineer's Notebook No. 246 contains survey for CSAH 11 running south to north on section line. Notes show corner marked by an iron in center of road with CSAH 12 east and west. Ties are the same as in 1959 and 1967.
- 1967 County Highway notes call for an iron and the following reference ties:
- | | | |
|-----------------|----|-------|
| PP | SW | 59.9' |
| 4" Spruce | SE | 78.0' |
| TP | NE | 50.3' |
| Steel sign post | SE | 47.1' |
- 1990 William Lunser, LS 9394, notes in Doc. No 201527 that the distance to the North 1/4 corner of Section 19 is 2614.91 feet.
- Paul E. Wellen, LS 10461, found a 3/4" iron pipe in the intersection of the centerlines of County Road 11 (running north and south) and County Road 12 (running east and west). Placed a cast iron monument over the 3/4" iron pipe and established new reference ties. A Certificate of Location (#201455) was recorded.
- 2001 Westwood Professional Services, Inc. found a broken off cast iron monument, down 6 inches, at the intersection of the centerlines of County Road 11 and County Road 12. We left the monument as found and established new ties. Position of the cast iron monument fit two ties from 1967. County Coordinates Obtained by GPS (Cast Iron Monument)
 NAD 83 (1996 Adjustment)
 N-180379.569
 E-515970.126
- 2008 Westwood Professional Services, Inc. found a broken off CIM coinciding with the 2001 coordinates. Left monument as found. CIM is accepted as marking the obliterated position for this corner.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 19, Township 38, Range 29, 4th P.M.
STATE OF MINNESOTA, County of BENTON


At the corner location shown on the sketch:

On 19 SEP. 1990 found a 3/4" IRON PIPE
DATE

left monument as found, lowered monument, removed monument (explain)

On 24 SEP. 1990 placed a COUNTY CAST IRON MONUMENT
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 11/14/91
SIGNATURE DATE

Registration No. 10461

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

Northwest corner of Section 19,
T 38 N, R 29 W, of the 4th Principal Meridian.

1. During the G.L.O. Survey of 1855, Mr. Oscar F. Davis, a U.S. Deputy Surveyor set a wood post to mark this corner.
2. A search of the Benton County Surveyor records indicated a iron with reference ties for the location of this corner.
3. On September 19, 1990, Paul E. Wellen & Associates, Inc., found a 3/4 inch iron pipe in the intersection of the center lines of 85th Avenue (County Road 11) (north-south) and County Road 12 (east-west). We lowered said 3/4 inch iron pipe and placed a cast iron monument at this location. We also established new reference ties as indicated.

201455

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

FEB 25 8 12 AM '91

ALICE C. ENGELMEYER
COUNTY RECORDER

BY Jed DEPUTY