

Certified, Filed and or Recorded on
JAN. 06, 2009 AT 04:03PM


Signed: CK
MARILYN J NOVAK
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 27, Township 38 N, Range 31 W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 11-09-05 found a 1/2" Iron Pipe (Flush with Ground, no cap)
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed a _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Sam J. DeLo Date 9-12-2008 License No. 40341
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

D273

East Quarter of Section 27, Township 38 North, Range 31 West, East Langola Township,
4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|------------|------------|-----------|
| 8" Bur Oak | S 23 1/2 W | 150 links |
| 8" Bur Oak | N 74 W | 155 links |
- 1977 William Lunser, LS 9394, set a 1/2" iron pipe at the intersection of fence lines running north, east, and west. He filed a Certificate of Location (#147076).
- 2002 No resurvey information was found on this corner in the Benton County records.
- 2005 Samuel DeLeo, LS 40341, 1/2" dia. iron pipe at the intersection of fence lines running east-west and north. Lunser's 1977 ties could not be found (overgrown), but the trees were still in place. New reference ties were recorded and coordinates were established on the corner.

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-172382.480
E-468256.992

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 27, Township 38, Range 31, _____ P.M.
STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On 1-16-1927 found fence lines to the North, East-West
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a 1/2 inch iron pipe
DATE

SKETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunsar 1-16-1927
SIGNATURE DATE

Registration No. 9394

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS ^{County Recorder}
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 9 A.M. on the 20th day of December A.D., 19 27


Register of Deeds F.A. Johnson
By County Recorder, Deputy

DOCUMENT NO. 147076

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 16 day of January, 1977
I did Set the East Quarter corner of Section 27,
Twp. 38, Rg. 31, Benton County, Minnesota, which
was evidenced by fence lines to the North, East-West

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of 1/2 inch iron pipe and that
I did establish witness or reference monuments as shown below:



147076

I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

William J. Johnson

Minn. Registration No. 9394

County Recorder
Office of the ~~Register of Deeds~~,
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 20 day of December, 1977 at 2 P.M.

F.G. Johnson
~~Register of Deeds~~

By County Recorder Deputy.