

MARILYN J. NOVAK
COUNTY RECORDER
BY CK DEPUTY

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

293725


2002 DEC 31 P 3: 56

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter _____ Corner of Section 34 , Township 38 , Range 31
4TH Principal Meridian, State of Minnesota, County of _____ BENTON

At the corner location shown on the sketch:

- On 07/19/01 found a cast iron monument
DATE
- left monument as found lowered monument removed monument (explain)
- On 11/15/2002 placed a PK at the location of the cast iron monument
DATE



New tree and power pole ties are to the head of a nail with a brass disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature] Date 11/27/02 License No. 12684

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

D341

The North Quarter Corner of Section 34, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

In June 1852, Edwin James Jr. set a wood post at this location and bearing trees were recorded.

8" Bur Oak	N 37 W	100 links
6" Bur Oak	S 16 E	17 links

The County Surveyors Records in Book 2, page 148 show an iron monument at the centerline of a road for the corner location with the following reference ties.

Fen Cor.	S	28
Fen Cor.	N	28

On August 25, 1972 William Lunser set a RR spike at the intersection of a fence line from the north and the centerline of an east/west road. A Certificate of Location (#133448) was filed.

On November 28, 1973 a distance of 2680.93 feet to the NE Corner Section 34 was measured, according to the Certificate of Location (#133446) for the NE Corner of Section 34.

On June 6, 1989 William Lunser found a 1/2" iron pipe and verified its location with distances to the SW and SE corners.

On December 8, 1989 William Lunser set a cast iron monument at the 1/2" iron pipe location. A Certificate of Location (#195971) was filed.

On July 19, 2001 Westwood Professional Services, Inc. found a cast iron monument at the centerline of County Road 2 (running east and west).

In April 2002 Westwood Professional Services, Inc. located monuments along County Road 2, prior to road construction, using GPS.

On November 15, 2002 Westwood Professional Services, Inc. set a PK at the location of the found cast iron monument after the road construction.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-169663.900
E-465543.736

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section 34, Township 38, Range 31, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 8-25-70 found a Rail Road Spike
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 12-8-89 placed a Benton County Cast Iron Mon.
DATE

SKETCH OF REFERENCE TIES



Not paid earlier
New ties

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William J. Lerner 1/5/90
SIGNATURE DATE

Registration No. 9394

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

8-25-1972 Lunser Survey Co. found a railroad spike at the quarter corner location, took ties and filed a certificate of location with the county recorder.

6-06-1989 Lunser Survey Co. found a $\frac{1}{2}$ " iron pipe at the above location, verified it's location with distances to the southwest and southeast section corners. Took ties and placed a cast iron mon.

1 9 5 9 7 1

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

JAN 11 8 37 AM '90

ALICE O. ENGELMEYER
COUNTY RECORDER


BY Jew DEPUTY

Langola

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 25 day of August, 1972
I did restore the north quarter corner of Section 34,
Twp. 38, Rg. 31, Benton County, Minnesota, which
was evidenced by fence line north - centerline road east & west

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of a railroad spike and that
I did establish witness or reference monuments as shown below:



133448

I hereby certify that the
above is true and correct
and that I am a registered
Land Surveyor under the laws
of the State of Minnesota.

William J. Johnson

Minn. Registration No. 9394

Office of the Register of Deeds,
Benton County, Minn.

I hereby certify that the within
instrument was filed for record
in this office on the 9th day of
February, 1973.

J. A. Johnson
Register of Deeds

By Marilyn Novak Deputy.