

Certified, Filed and or Recorded on
July 06, 2010 AT 03:13PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Northeast Corner of Section 11, Township 38 North, Range 31 West, Fourth Principal Meridian,
Benton County, Minnesota.

At this corner location shown on the sketch:

On 8/11/2008 found a 1/2" iron pipe capped RLS 12236

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a Licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock
Benton County Surveyor
License No. 19552

Date: 7/6/2010

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552

Statement of Evidence:

D112

Northeast Corner of Section 11, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post in a mound at the corner location.

No Date County Surveyor's Record Book 2, page 86, notes a **stone** at the corner location.

2004 Dave Regan, LS 12236 worked in the SW1/4 of Section 1, dug for the stone but no evidence was found. He set an iron pipe capped RLS 12236 at the apparent intersection of fence lines north, south and east. Reference Job. No. 04-0561.00 B. 56, P. 30 dated 12/30/04 and 1/27/05

2008 Westwood Professional Services, Inc. found Regan's iron pipe capped RLS 12236. Iron pipe fits longstanding fence line occupation north, south and along the south lines of Section 1 and 2. The iron pipe is accepted as marking the obliterated position.

County Coordinates Obtained by GPS
NAD 83 (96 Adjustment)
N-190898.994
E-473156.213