

Certified, Filed and or Recorded on
Oct. 31, 2008 AT 08:22AM


Signed: Marilyn J Novak
MARILYN J NOVAK G V
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 27, Township 38, Range 31
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-26-08 found a 1/2" IRON PIPE
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Ch. H. [Signature]
Deputy County Surveyor
License No. 43932

Date: 10/14/08
PAGE 1 OF 2

Benton County Surveyor's Office
 Chris Hoglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

D272

Northeast Corner of Section 27, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Bur Oak	S 57 E	533 links
10" Bur Oak	N 32 E	350 links

1975 County Highway ties for a set 3/4" iron pipe flush in the centerline of a west/east trail:

N & D RR tie F.P.	N	31.30
N & D Fen Cor	S	32.18
N & D 8" Pine	SW	39.24

In line with fence line north and south.

1977 William Lunser, LS 9394, found a 1/2" iron pipe on a fence line north/south. He filed a Certificate of Location (#147075).

2008 Westwood Professional Services, Inc. found a 1/2" iron pipe at the corner location. Corner fits longstanding occupation and both 1975 and 1977 ties. This location is accepted as marking the obliterated corner location.
 County coordinates obtained by GPS
 County Coordinates
 NAD 83 (1996 Adjustment)
 N- 174982.311
 E- 468163.732

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I did find NE Corner of Section 27, Township 38, Range 31, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On 1-16-1977 found a 1/2 inch iron pipe
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a Left as found
DATE

SKETCH OF REFERENCE TIES


Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunsar 1-16-1977
SIGNATURE DATE

Registration No. 9394

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS ^{County Recorder}
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 9 A .M. on the Saturday of December A.D., 19 77


Register of Deeds F. G. Johnson
^{County Recorder}
By _____, Deputy

DOCUMENT NO. 147075

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 16 day of January, 1977
 I did Find _____ the North East corner of Section 27,
 Twp. 38, Rg. 31, Benton County, Minnesota, which
 was evidenced by 1/2 inch iron pipe

I further certify that in order to perpetuate said corner I did
 at the exact location thereof place a permanent marker consisting
 of _____ and that
 I did establish witness or reference monuments as shown below:



147075

I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

William J. Jensen

Minn. Registration No. 9394

County Recorder
 Office of the ~~Register of Deeds~~,
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 20 day of December, 1977 at 9 A.M.

F. G. Johnson
~~Register of Deeds~~ County Recorder

By _____ Deputy.