

Certified, Filed and or Recorded on
Nov. 07, 2008 AT 02:21PM

Signed: JM
MARILYN J NOVAK JVN
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 19, Township 37N, Range 29W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10/29/08 found a 1/2" IRON PIPE OPEN DOWN 0.3'

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oly
Deputy Benton County Surveyor
License No. 45872

Date: 11/06/2008

Benton County Surveyor's Office
Jason W. Oberg, Deputy County Surveyor
Minnesota License No. 45872

Statement of Evidence:

H193

East Quarter Corner of Section 19, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

20" Elm	S 50 W	219 links
9" Bur Oak	S 41 ½ W	208 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 The County Surveyor's Office searched and found a ½" iron pipe along the centerline of a north-south gravel road (County Road 83). Position gives 2632.48 ft. and 2642.48 ft. to the NE and SE Corners, respectively, and lies 2.39 ft. west of a straight line. The Surveyor accepts the position as marking the best evidence and updated ties.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-145609.370
E-516014.229