

A 361673

Certified, Filed and or Recorded on
Nov. 07, 2008 AT 02:22PM


Signed: [Signature]
MARILYN J NOVAK
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 17, Township 37N, Range 29W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/29/08 found a CAST IRON MONUMENT DOWN 1.0'
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



8
17



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature]
Deputy Benton County Surveyor
License No. 45872

Date: 11/06/2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:

H171

North Quarter Corner of Section 17 Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

12" Sugar	S 85 E	7 links
15" Sugar	N 28 ½ E	14 links

1987 Paul Wellen, LS 10461, found a ½ " iron pipe, 2 feet south of east-west centerline and in line with fence line north. He replaced the pipe with a cast iron monument and filed a Certificate of Location (Doc. No. 184285). His notes give measurements of 2668.59 feet to the NW corner and 2668.00 feet to the NE corner of Section 17.

2002 No resurvey information was found on this corner in the Benton County records.

2008 The County Surveyor's Office searched and found Wellen's 1987 cast iron monument. Position falls on the centerline of an east-west gravel road (95th St. NE), and on line with a tree line to the north. Distances to the NW and NE Corners measures 2668.70 ft. and 2668.01 ft., respectively. Corner falls 15.37 ft. north of a straight line. The Surveyor accepts the position as marking the best evidence and ties were updated.

County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-153558.706
 E-518833.808

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter _____ Corner of Section 17, Township 37, Range 29, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 4-14-87 found a 1/2 inch iron pipe, 8 inches deep, 2 feet South of Center Line of 95th St NE, Opposite fence line to North
 - left monument as found, lowered monument, removed monument (explain)
- On 6-8-87 placed a Cast Iron Monument

SKETCH OF REFERENCE TIES



1 8 4 2 8 5

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

Aug 5 11 26 AM '87

ALICE O. ENGELBREYER
COUNTY RECORDER

BY [Signature] DEPUTY

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] _____ 6-29-87 _____
SIGNATURE DATE

Registration No. 10461

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M. on the _____ day of _____ A.D., 19 _____

County Recorder _____
By _____, Deputy

DOCUMENT NO. _____