

Certified, Filed and or Recorded on
Nov. 07, 2008 AT 02:28PM


Signed: *JU*
MARILYN J NOVAK *G V J*
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 19, Township 37N, Range 29W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/29/08 found a CAST IRON MONUMENT DOWN 0.8'
- left monument as found lowered monument removed monument (explain)
- On 10/29/08 placed an PK NAIL WITH BENTON COUNTY SURVEYOR DISK OVER CAST IRON MONUMENT FLUSH WITH ROAD SURFACE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Jan W. Oly*
Deputy Benton County Surveyor
License No. 45872

Date: 11/06/2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:

H191

North Quarter Corner of Section 19, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

13" Linden	N 27 ½ W	10 links
14" Blk Oak	S 51 ½ E	17 links

1939 County Engineer's Notebook No. 158 contains road survey for CAR No. 20 running east to west along the section line. Corner is shown as a spike set in center of road with fences north and south. Ties:

FP	N	21.5'
FP	NE	26.25'

Stationing gives distances of 2648.2 feet to the NE corner and 2616.7 feet to the NW corner with a delta angle of 0-32' left.

1979 Paul Wellen, LS 10461, found a ¾" iron pipe in center of east-west road and power line north-south. He set a cast iron monument and filed a Certificate of Location (Doc. No. 160208). His notes give a measurement of 2618.70 feet to the NW corner of Section 19.


2008 The County Surveyor's Office searched and found Wellen's 1979 cast iron monument along centerline of an east-west gravel road (County Road 43). Position gives a distance to the NW Cor. of 2618.59 ft. and a deflection (east to west) of 0°23'36"-left, which agrees with 1939 measurements. Thus, the cast iron monument is accepted as marking the best evidence. Ties were updated.

County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-148209.559
 E-513418.786

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 4 day of April, 19 79
 I did find _____ the N1/4 corner of Section 19,
 Twp. 37, Rg. 29, Benton County, Minnesota, which
 was evidenced by 3/4 inch iron pipe in the center line of a east-west road
opposite a power line North-south.

I further certify that in order to perpetuate said corner I did
 at the exact location thereof place a permanent marker consisting
 of a Benton County Cast Iron Monument and that
 I did establish witness or reference monuments as shown below:



160208

79-22 B-11 P-148

Office of the County Recorder,
Benton County, Minn.

I hereby certify that the within instrument
 was filed for record in this office on the
10th day of September, 1981 at 2 P.M.

I hereby certify that the above
 is true and correct and that I am
 a registered Land Surveyor under
 the laws of the State of Minnesota.

[Handwritten Signature]

Minn. Registration No. 10461

F.A. Johnson
 County Recorder

By _____ Deputy.