

Certified, Filed and or Recorded on
Oct. 07, 2008 AT 02:48PM


Signed: BW
MARILYN J NOVAK B V R
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 16, Township 36N, Range 28W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09/30/08 found a 1/2 INCH IRON PIPE WITH CAP NO. 9394
1.4 FT ± EAST OF FENCE
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jason W. Gley
Deputy Benton County Surveyor
License No. 45872

Date: 10/06/08

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:

J161

The North Quarter Corner of Section 16, Township 36 North, Range 28 West,
 Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

9" Tamarack	S 52 W	28 links
8" Blk Ash	N 20 W	39 links

2002 No resurvey information has been found on this corner in the Benton County records.

2008 The County Surveyor's Office searched and found a ½" iron pipe capped "9394" approximately 1.4 ft.± east of an old north-south fence line. Position falls 0.20 ft. south and 0.02 ft. east of a lost position and is accepted by the Surveyor as the best evidence. Ties were made and the position recorded with GPS.

County Coordinates obtained by GPS
 NAD 83 (1996 Adjustment)
 N-121591.541
 E-555666.809