

Certified, Filed and or Recorded on
Oct. 07, 2008 AT 02:46PM


Signed: BW
MARILYN J NOVAK EV
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 24, Township 36N, Range 28W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/01/08 found a CAST IRON MONUMENT
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. O'Leary
Deputy Benton County Surveyor
License No. 45872

Date: 10/06/08

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:**J242**

The Northeast Corner of Section 24, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

6" Tamarack	N 24 E	21 links
6" Tamarack	S 32 E	2 links
6" Tamarack	S 17 W	18 links
6" Tamarack	N 30 W	15 links

Line trees were noted as a 12" Basswood South 20.15 chains and a 6" Elm North 16.85 chains.

1965 Minnesota DNR survey notes show corner at the intersection of an old fence line north, south, and east and the centerline of an old road to the west.

1988 William Lunser, LS 9394, found corner fence post broken off. He dug and found remaining part of corner post and replaced with a Cast Iron Monument. He filed a Certificate of Location (Doc. No. 191249).

1996 County Coordinates from John Oliver & Associates by traverse:
 NAD 83 (1986 Adjustment)
 N- 116498.589
 E- 574203.570

2002 No resurvey information was found on this corner in the Benton County Surveyor's records and Mille Lacs County records have not been checked.

2008 The Benton County Surveyor's Office searched and found a cast iron monument at the approximate P.I. location of an old east-west, north-south path. Position fits Lunser's ties from 1988. Surveyor accepts Lunser's evidence and updated ties.

County Coordinates
 NAD 83 (1996 Adjustment)
 N-116499.031
 E-574204.204

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 24, Township 36, Range 28, 4th P.M.

STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 10-13-1988 placed a Benton County Cast Iron Monument
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William J. Lauer 12/15/88
SIGNATURE DATE

Registration No. 9394

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

- 5-21-1965 The Dept. of Natural Resources notes state that the location of this section corner is at the intersection of a old Fence line North, South, and East and the centerline of a old road to the West.
- 10-13-1988 Found corner post of fence broken off. Dug and found remaining part of corner post and replaced same with a Cast Iron Monument.

191249

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

JAN 12 11 59 AM '69

ALICE O. ENGELMEYER
COUNTY RECORDER

BY *Jew* DEPUTY