

Certified, Filed and or Recorded on
Oct. 07, 2008 AT 02:47PM


Signed: BW
MARILYN J NOVAK BV
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 33, Township 36, Range 28
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09/29/08 found a _____
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oley
Deputy Benton County Surveyor
License No. 45872

Date: 10/06/08

PAGE 1 OF 2

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:

J332

Northeast Corner of Section 33, Township 36 North, Range 28 West, Glendorado Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|-----------|-------|------------|
| 7" W Oak | S 2 E | 1741 links |
| 18" W Oak | S 1 W | 1736 links |
- 1901 County Surveyor's Record Book 1, page 61 and Record Book A, Map No. 40 is a survey of Section 27 by John Whilt, which shows this corner.
- 1929 County Surveyor's Book 1, page 71 and Record Book A, Map No. 49 shows a survey of Section 28 by M.B. Lang. Corner is shown, but no information given.
- 1933 County Engineer's notebook No. 70 shows road survey by H. G. Elletson. Corner is shown as spike in center of road intersection with roads running north and west with ties:
- | | | |
|------|-----------|-------|
| F.P. | East | 37.7' |
| Pop. | N 65-00 W | 74.1' |
| Pop. | N 45-00 W | 72.7' |
- 1935 County Engineer's Notebook No. 92 contains survey for SAR No. 7 running north to south. Notes corner as a spike with road west and fence east. Ties:
- | | | | | | |
|-----|----|-------|-----|----|--------|
| Hub | NW | 43.8' | Hub | SW | 37.35' |
|-----|----|-------|-----|----|--------|
- No Date County Ties to Iron Pipe:
- | | | |
|----|----|-------|
| TP | NE | 41.4 |
| TP | SE | 133.5 |
| PP | SW | 44.0 |
- 1991 Dennis Taylor, LS 15233, found a RR spike set by Benton County Highway crew in 1978 at centerline of roads north, south, and west. He replaced the RR spike with a cast iron monument and filed a Certificate of Location (Doc. No. 212586).
- 2001 Westwood Professional Services, Inc. found a CIM in centerline of roads north, south, and west.
- 2005 Sam DeLeo, LS 40341, reported finding the CIM and County Coordinates obtained by GPS:
 NAD 83 (1996 Adjustment)
 N- 105663.764
 E- 558568.870
- 2008 The County Surveyor's Office searched and found a PK Nail over the cast iron monument set by Taylor in 1991. The Surveyor accepts the position as found and updated ties from Taylor's 1991 certificate of location.
- County Coordinates obtained by GPS:
 NAD 83 (1996 Adjustment)
 N- 105663.808
 E- 558569.092

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 33, Township 36, Range 28, 4th P.M.

STATE OF MINNESOTA, County of BENTON


At the corner location shown on the sketch:

On 11-26-91 found a R.R. SPIKE (SET BY BENTON CO. HWY. DEPT. 12-12-78)
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a CAST IRON MONUMENT
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Dennis V. Taylor 1-12-93
SIGNATURE DATE

Registration No. 15233

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

Found railroad spike flush with the surface at the northeast corner of Section 33, Township 36, Range 28, set by Benton County Highway Department on 12-12-78 at the centerline of Highway # 48 and the centerline of Highway #7.

Per G. Holter, owner of the SE 1\4 of Section 29, Township 36, Range 28, the intersection of Highway # 48 and Highway # 7 is the Southeast Corner of his property. Both roads were built on the section lines, per his observation, at the time of the original road construction.

No bearing trees referenced in the original plat notes were located.

Set Cast Iron Monument, flush with road surface, at the location of Railroad spike previously set by Benton County Highway Department.

212586

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

JAN 13 9 41 AM '99

ALICE G. ENGELMEYER
COUNTY RECORDER

BY *JW* DEPUTY