

A 361458

Certified, Filed and or Recorded on  
Nov. 04, 2008 AT 12:31PM

Signed: BW  
MARILYN J NOVAK G V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 21, Township 38, Range 30  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-20-08 found a 1/2" IRON PIPE WITH BUSTED CAP

left monument as found       lowered monument       removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]  
Deputy County Surveyor  
License No. 43932

Date: 11/3/08

Statement of Evidence:

C213

East Quarter Corner of Section 21, Township 38 North, Range 30 West, Graham Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this corner and set a wood and bearing trees were recorded.

8" Blk Oak                      S 20 E                      279 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services found 1/2" iron pipe with a broken cap ~2 feet west of the centerline of 45<sup>th</sup> Ave. NE and on line with a fence line to the west. Monument is on line between the NE and SE corners of Section 21 and 31 feet north of the lost position. Iron pipe fits longstanding occupation to the west and fits relatively well with doubled 1/16<sup>th</sup> distance to the north. 1/2" iron pipe is accepted as marking the obliterated position for this corner.

County Coordinates obtained by GPS

NAD 83 (1996 Adjustment)

N- 177767.655

E- 494739.731