

A 362576

Certified, Filed and or Recorded on
Dec. 24, 2008 AT 08:55AM

Signed: BW
MARILYN J NOVAK B V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 10, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:



On 10-15-08 found a 1/2" IRON PIPE # 19552

left monument as found lowered monument removed monument (explain)

On _____ placed an _____

FIELD

FIELD



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature]
Deputy County Surveyor
License No. 43932

Date: 12/17/08

Statement of Evidence:

C101

North Quarter Corner of Section 10, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office set a wood post at this location and bearing trees were recorded:

12" Aspen	N 21 E	31 links
10" Aspen	S 75 W	16 links

1908 County Surveyor's Record Book 2, page 162, shows corner was used by M.J. Cleveland to establish the center of Section 3. No corner information given.

1964 County Engineer's Notebook No. 276 contains a road survey for CSAH No. 22 running west to east on section line. Notes do not show this corner and stationing gives distance of 5321.9 feet between section corners.

2008 Westwood Professional Services, Inc. found a ½" iron pipe capped 19552 at the lost position for this corner. Measured 2660.16 feet to the NE and NW corners of Section 10. Position fits occupation along the north/south quarter line of section 3. Iron pipe capped 19552 is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-191023.558
E-496861.926