

Office of the County Recorder, BENTON County, Minnesota  
I hereby certify that the within instrument was filed for record in this office on the  
\_\_\_\_\_ day of \_\_\_\_\_, 200\_\_.

COUNTY RECORDER

By \_\_\_\_\_ Deputy.

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section 21, Township 38, Range 30  
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 12/2001 found a nothing  
DATE

left monument as found     lowered monument     removed monument (explain)

On 1/3/02 placed a 1/2"x12" iron pipe capped #10461 at the intersection of  
DATE  
the centerline of County Road 12 and a fence and field line from the south



Ref. Job #

Ties that are found and in good condition are noted as 'existing'. New tree and power pole ties are to the head of a nail with a brass disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature] Date 4/18/02 License No. 10461

Title:  Land Surveyor     Professional Engineer     County Surveyor     County Engineer

Statement of Evidence:

C211

The North Quarter Corner of Section 21, Township 38 North, Range 30 West, Graham Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

In 1852, Edwin James Jr. a wood post was set at this location and bearing trees were recorded.

15" Burr Oak N 25 W 1030 links

The County Surveyors records in Book 2, page 198 show a nail at this location with the following reference ties.

F.P. NE 35.8  
F.P. NW 39.4

In December 2001, Westwood Professional Services, Inc. searched the area for a monument, bearing trees, and ties and found no evidence of any.

On January 3, 2002 Westwood Professional Services, Inc. established the North Quarter Corner of Section 21 at the intersection of the centerline of County Road 12 (running east and west) and a fence line and field line from the south. We set a 1/2" X 12" iron pipe capped #10461 at the corner location. The established corner position is 5.48 feet north and 15.03 feet west of the lost position. Corner is considered reestablished by obliterated means.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-180405.569  
E-491945.044

MARILYN J. ROYER  
COUNTY RECORDER  
BY Marilyn J. Novak DEPUTY

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON

285640

2002 MAY -7 A 8:28