

Office of the County Recorder, BENTON County, Minnesota
I hereby certify that the within instrument was filed for record in this office on the
____ day of _____, 200____.

COUNTY RECORDER

By _____ Deputy.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section 24, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 12/2001 found a nothing
DATE

left monument as found lowered monument removed monument (explain)

On 1/3/02 placed a 1/2"x12" iron pipe capped #10461 at the intersection of
DATE
the centerline of County Road 12 and fence lines from the north and south



Ref. Job #

Ties that are found and in good condition are noted as 'existing'. New tree and power pole ties are to the head of a nail with a brass disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature] Date 4/18/02 License No. 10461

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

C241

The North Quarter Corner of Section 24, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

In 1852, Edwin James Jr. set a wood post was set at this location and bearing trees were recorded.

16" Aspen N 8 E 18 links
8" Aspen S 8 E 29 links

The County Surveyors records in Book 2, page 204, shows a spike in the center of road opposite fence line with no date.

On July 19, 2001 Westwood Professional Services, Inc. searched the area and found no trace of a monument at this location.

In December 2001 Westwood Professional Services, Inc. located fences and occupation throughout Sections 13 & 24, T38N, R30W.

On January 3, 2002 Westwood Professional Services, Inc. set a 1/2" X 12" iron capped #10461 at the intersection of the centerline of County Road 12 (running east and west) and fence lines extended from the north and the south. This corner position is 5.03 feet north and 1.36 feet east of the lost position. Corner is considered reestablished by obliterated means.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-180448.055
E-507981.652

MARILYN J. NOVAK
COUNTY RECORDER
BY Marilyn J. Novak
DEPUTY

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

285643

2002 MAY -7 A 8:29