

Certified, Filed and or Recorded on
Nov. 04, 2008 AT 12:37PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 25, Township 38, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-22-08 found a 1/2" IRON PIPE WITH CAP ?

left monument as found lowered monument removed monument (explain)

On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Benton County Surveyor's Office
 Chris Hoglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

C251

North Quarter Corner of Section 25, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post was set at this location and bearing trees were recorded.

8" Blk Oak	N 20 E	18 links
8" Blk Oak	S 54 W	15 links

2002 No resurvey information has been found on this corner in the Benton County records.

2008 Westwood Professional Services, Inc. found a ½" iron pipe with unreadable cap. Location falls 2.5 feet north of the centerline of 135th St. NE and in line with fence/tree/rock line to the north and fence south. Measured 2610.37 feet to the NW corner and 2605.90 feet to the NE corner of Section 25. Iron pipe is 2.5 feet SE of lost position. Iron pipe is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N-175069.348
 E-508208.114