

Certified, Filed and or Recorded on
Dec. 24, 2008 AT 08:46AM


Signed: BW
MARILYN J NOVAK
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 35, Township 38N, Range 28W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/16/08 found a CAST IRON MONUMENT DOWN 0.6'
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jason W. Gley
Deputy Benton County Surveyor
License No. 45872

Date: 12/09/2008

Statement of Evidence:

A352

Northeast Corner of Section 35, Township 38 North, Range 28 West, Granite Ledge Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|-----------|--------|----------|
| 24" Sugar | S 89 E | 80 links |
| 10" Birch | N 62 W | 34 links |
- 1902 County Surveyor's Record Book A, Map No. 37, shows a survey of Section 25 by John Whilt. Corner is shown, but no information.
- No Date County Surveyor's Record Book 2, page 358, notes the following additional bearing tree.
- | | | |
|-------------|------------|-----------|
| 10" W. Pine | S 85 3/4 E | 127 links |
|-------------|------------|-----------|
- 1937 County Engineer's Notebook No. 82 contains a road survey for SAR No. 9 running south to north. Notes show corner marked by a spike in road intersection with ties:
- | | | |
|----|----|-------|
| FP | NW | 49.3' |
| FP | SW | 39.9' |
- 1962 County Engineer's Notebook No. 269 contains a road survey for CSAH No. 9 running south to north. Notes show corner marked by an iron in center of road with town road east and west. Ties:
- | | | |
|--------------------|----|-------|
| PP | SW | 55.8' |
| 2 nd FP | SE | 61.5' |
| TP | NE | 41.7' |
- 1962 County Surveyor's Record Book 2, page 378, notes an iron at the corner with the same ties as above in 1962. (Notation shows same in 1969 and 1972)
- 2000 Westwood Professional Services, Inc. set an iron pipe capped RLS #23002 at the intersection of the centerlines of County Road 9 (running north and south) and 125th Street NE (running east and west).
- 2001 Westwood Professional Services, Inc. found an iron pipe with a busted cap at the intersection of the centerlines of County Road 9 (running north and south) and 125th Street NE (running east and west). We removed the iron and set a cast iron monument at the location and established reference ties. Tie to PP to the SW checked within a foot, but could be a different pole. No evidence found of the W. Pine BT.
- County Coordinates by GPS to CIM
NAD 83 (1996 Adjustment)
N- 169632.977
E- 568205.201
- 2008 The County Surveyor's Office searched and found the cast iron monument as reported by Westwood Professional Services, Inc. in 2001. Distance to the E 1/4 Cor. of Sec. 35, from 1962 stationing gives 2641.5 ft, vs. 2639.99 ft measured, while the distance to the E 1/4 Cor. of Sec. 26 from 1962 stationing gives 2623.0 ft, vs. 2621.50 ft measured. The discrepancies share a common index factor, whereas the 2008 measurements divided by the 1962 measurements give 0.99942835, or 1 part in 1,750. Position checks for occupation and is accepted as the best evidence. Ties were updated. Coordinates obtained agree with those reported by Westwood Professional Services, Inc. in 2001.

Certified, Filed and or Recorded on
Dec. 16, 2008 AT 01:49PM


Signed: BW
MARILYN J NOVAK (G V)
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 35, Township 38N, Range 28W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 10/16/08 found a CAST IRON MONUMENT DOWN 0.6'
- left monument as found lowered monument removed monument (explain)
- On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jan W. Oly
Deputy Benton County Surveyor
License No. #5872

Date: 13 Nov 2008

Benton County Surveyor's Office
 Jason W. Oberg, Deputy County Surveyor
 Minnesota License No. 45872

Statement of Evidence:**A352**

Northeast Corner of Section 35, Township 38 North, Range 28 West, Granite Ledge Township, 4th
 Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|-----------|--------|----------|
| 24" Sugar | S 89 E | 80 links |
| 10" Birch | N 62 W | 34 links |
- 1902 County Surveyor's Record Book A, Map No. 37, shows a survey of Section 25 by John Whilt. Corner is shown, but no information.
- No Date County Surveyor's Record Book 2, page 358, notes the following additional bearing tree.
- | | | |
|-------------|------------|-----------|
| 10" W. Pine | S 85 3/4 E | 127 links |
|-------------|------------|-----------|
- 1937 County Engineer's Notebook No. 82 contains a road survey for SAR No. 9 running south to north. Notes show corner marked by a spike in road intersection with ties:
- | | | |
|----|----|-------|
| FP | NW | 49.3' |
| FP | SW | 39.9' |
- 1962 County Engineer's Notebook No. 269 contains a road survey for CSAH No. 9 running south to north. Notes show corner marked by an iron in center of road with town road east and west. Ties:
- | | | |
|--------------------|----|-------|
| PP | SW | 55.8' |
| 2 nd FP | SE | 61.5' |
| TP | NE | 41.7' |
- 1962 County Surveyor's Record Book 2, page 378, notes an iron at the corner with the same ties as above in 1962. (Notation shows same in 1969 and 1972)
- 2000 Westwood Professional Services, Inc. set an iron pipe capped RLS #23002 at the intersection of the centerlines of County Road 9 (running north and south) and 125th Street NE (running east and west).
- 2001 Westwood Professional Services, Inc. found an iron pipe with a busted cap at the intersection of the centerlines of County Road 9 (running north and south) and 125th Street NE (running east and west). We removed the iron and set a cast iron monument at the location and established reference ties. Tie to PP to the SW checked within a foot, but could be a different pole. No evidence found of the W. Pine BT.
- County Coordinates by GPS to CIM
 NAD 83 (1996 Adjustment)
 N- 169632.977
 E- 568205.201
- 2008 The County Surveyor's Office searched and found the cast iron monument as reported by Westwood Professional Services, Inc. in 2001. Distance to the E ¼ Cor. of Sec. 35, from 1962 stationing gives 2641.5 ft, vs. 2639.99 ft measured, while the distance to the E ¼ Cor. of Sec. 26 from 1962 stationing gives 2623.0 ft, vs. 2621.50 ft measured. The discrepancies share a common index factor, whereas the 2008 measurements divided by the 1962 measurements give 0.99942835, or 1 part in 1,750. Position checks for occupation and is accepted as the best evidence. Ties were updated. Coordinates obtained agree with those reported by Westwood Professional Services, Inc. in 2001.