

Certified, Filed and or Recorded on
Dec. 16, 2008 AT 01:58PM

Signed: BW
MARILYN J NOVAK G V
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER




EAST QUARTER Corner of Section 4, Township 37N, Range 30W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 11/17/08 found a 1/2" IRON PIPE WITH CAP #9394 UP 0.2'

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature M. Lewis
Deputy Benton County Surveyor
License No. 46170

Date: 12/12/08

Benton County Surveyor's Office
Nancy H. Lewis, Deputy County Surveyor
Minnesota License No. 46170

Statement of Evidence:

G043

East Quarter Corner of Section 4, Township 37 North, Range 30 West, 4th Principal Meridian, (Mayhew Lake Township) Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

8" Bur Oak	S 23 W	30 links
6" Aspen	N 78 E	29 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 The Benton County Surveyor's Office searched and found a ½" capped iron pipe (#9394) at the intersection of north-south and east-west fence lines. The position gives a distance to the NE Cor. and the SE Cor. of 2880.95 feet and 2650.95 feet. Position agrees with surrounding long standing occupation. Surveyor accepts ½" iron pipe as best evidence of obliterated corner and updated ties.

Coordinates Obtained by GPS to ½" I.P.
NAD 83 (1996 Adjustment)
N- 161480.058
E- 495090.485