

A 379527

Certified, Filed and or Recorded on
JAN. 18, 2011 AT 01:52PM

Signed: OK
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 13, Township 37 N, Range 30 W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 09/08/2010 found a 1/2" solid pin 0^{3/4}' below road Surface

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock
Benton County Surveyor
License No. 19552

Date: 17 Jan. 2011

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:**G133**

East Quarter Corner of Section 13, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1849 Corner established by Original US General Land Office survey and marked by a wood post with bearing trees noted as.

6" Ironwood	S 22 E	27 links
18" W Oak	N 54 W	39 links

Line trees were noted as a 18" Elm, South, 19.80 chains and a 6" Poplar, North, 19.63 chains.

1994 David Regan, LS 12236, found a 1/2" iron pin on the centerline of road north/south and a fence line west and +/- 28 feet south of a field line east. He filed a Certificate of Location (#231243).

2008 Westwood Professional Services found a 1/2" iron pin on the centerline of road north/south, 8 feet south of a fence line west and +/- 29 feet south of a fence line east. The found pin fits occupation lines at the sixteenth north within a foot and south within 3 feet and fits a split of the distances between section corners within 3.5 feet. The iron pin is accepted as marking the obliterated corner position.

Coordinates Obtained by GPS
 NAD 83 (1996 Adjustment)
 N- 150815.653
 E- 510819.970

2010 The Benton County Surveyor's Office found the 1/2" iron pin 0.3 feet below the road surface, established references as shown and verified the 2008 coordinates.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter _____ Corner of Section 13, Township 37, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 8/18/94 found a 1/2" Iron pin on centerline of road North-South and
DATE
fence line West. 28'+ South of field division East
 - left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David J. Reyan 3/27/95
SIGNATURE DATE

Registration No. 12236

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

The G.L.O. survey was done in 1849 by Theodore Conkey.

The County Surveyors records were searched with no reference to this corner.

On 8/94, Regan Land Surveyors, Inc. searched and dug the area and found a 1/2" iron pin at this corner and made ties.

231243

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

OCT 20 3 02 PM '95

ALICE G. ENGBLEMEYER
COUNTY RECORDER

BY Maw DEPUTY *RM*