

Certified, Filed and or Recorded on
Mar. 11, 2009 AT 10:14AM


Signed: JN
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 10, Township 37N, Range 30W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 12/19/08 found a 1/2" OPEN IRON PIPE UP 0.1'
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 3/6/09

Statement of Evidence:**G101**

North Quarter Corner of Section 10, Township 37 North, Range 30 West, 4th Principal Meridian, (Mayhew Lake Township) Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.

10" Aspen	N 19 W	14 links
8" Aspen	S 51 ½ E	72 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services, Inc. found a ½" iron pipe at the intersection of old fences north/east/west. Measured 2642.94 feet to the NW corner and 2636.01 feet to the NE corner of Section 10. Position is 3.46 feet east of the lost position and 0.88 feet south. Position fits well with lost position and old fence lines are longstanding evidence of section line location. ½" iron pipe is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N- 158807.970

E- 497758.616