

Certified, Filed and or Recorded on
Mar. 16, 2010 AT 12:37PM


Signed: CK
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 19, Township 37, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-1-06 found a CAST IRON MONUMENT
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock Date 3/16/2010 License No. 19552
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

G191

North Quarter Corner of Section 19, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

-
- 1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.
- | | | |
|-------------|------------|-----------|
| 24" Blk Oak | S 35 1/2 W | 50 links |
| 8" Blk Oak | N 65 1/2 W | 150 links |
- 1879 County Surveyor's Record Book 1, page 233, notes that Richard Cronk did a road survey from this corner and he notes a post at the corner.
- 1979 Paul Wellen, LS 10461, found a 1" iron pipe at intersection of fence lines north and west. He replaced it with cast iron monument and filed a Certificate of Location (#154383). Notes show he measured 2825.25 feet to the NW corner.
- 2006 Westwood Professional Services Inc. found a cast iron monument on the east side of a corner fence post and on line with distant tree line to the east. Distances measure 75 feet of GLO west and 112 feet long of GLO to the east. The closing distances along the north and west tier of sections in the townships of Benton County typically measure long of GLO distance. The CIM is accepted as marking the corner position.
- Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-148166.948
E-481553.256
- 2009 Westwood Professional services found the CIM, established reference ties and verified the 2006 coordinates.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North 1/4 Corner of Section 19, Township 37, Range 30, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Filed under South 1/4 Section 18 , T37 R30

Certificate # 154383

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE DATE

Registration No. _____

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____