

Office of the County Recorder, BENTON County, Minnesota
I hereby certify that the within instrument was filed for record in this office on the
 day of , 200 .

COUNTY RECORDER

By _____ Deputy.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section 6, Township 37, Range 28
4TH Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 10/24/01 found a 1/2" Solid Pin under a 1/2" Open
DATE

left monument as found lowered monument removed monument (explain)

On 10/24/01 placed a Cast Iron Monument over the 1/2" Solid Pin
DATE



Ref. Job #20005753

Ties that are found and in good condition are noted as 'existing'. New tree and power pole ties are to the head of a nail with a brass disk marked "Corner Tie".

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature] Date 10/14/02 License No. 12684

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence:

The North Quarter Corner of Section 6, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

In 1849, Theodore Conkey set a wood post at the corner location and bearing trees were recorded.

14" B. Ash S 8 W 10 links
10" B. Ash N 6 E 35 links

In 1955, notes in Book 2, page 396 refer to an iron with the following reference ties.

P.P. NW 41.55
T.P. SW 14.78
2nd F.P. S 54.6

In 1956 it is noted that the section corner location is on a fence line that is running north and south.

On December 26, 1995 William Lunser found a PK at the intersection of fence lines from the north and south and a township road east and west. He replaced the PK with a 1/2" iron pipe and established ties. A Certificate of Location (#234175) was filed.

On September 5, 2000 Westwood Professional Services, Inc. found a 1/2" iron pipe at the intersection of County Road 5 (running east and west) and a fence line from the south.

On October 24, 2001 Westwood Professional Services, Inc. found a 1/2" iron pipe over a 1/2" solid pin. Removed the 1/2" iron pipe and set a cast iron monument over the 1/2" solid pin and established reference ties.

MARILYN J. NOVAK
COUNTY RECORDER
BY Marilyn J. Novak DEPUTY

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

291188


2002 OCT 30 P 3: 23

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER corner of Section 6, Township 37, Range 28, 4th P.M.
Benton County, Minnesota.

On Dec 26, 1995, A 1/2 inch iron pipe (I.P.) was placed at this location.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunser 3/13/96
William F. Lunser, L.S. Date
Mn Reg No 9394

FB; 150/24 DISC; 14

OFFICE OF THE COUNTY RECORDER
Benton County, Minnesota

I hereby certify that this document was filed in this office at ___:___ M. on the ___ day of _____, 19___.

County Recorder _____

By _____ Deputy


DOCUMENT NO. _____

STATEMENT OF EVIDENCE:

No records were found to indicate use or remonumentation of this corner after its original placement by the U.S. Government Survey.

A search of the area revealed a "PK" nail of unknown origin which coincides with lines of occupation consisting of fence lines north and south and a township road east and west.

After comparing measured distances to those of the G.L.O. I consider this marker to be the best evidence of the original corner and replaced it with a 1/2 inch iron pipe.


William F. Lunser, L.S.

2 3 4 1 7 5

DEPT. COUNTY RECORDER
SOUTH COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

APR 10 2 34 PM '96

ALICE O. ENDELMAYER
COUNTY RECORDER

BY  DEPUTY X M